

## **SERVICE INFORMATION NO. SI 42NG-023/1**

### **SUPERSEDES SERVICE INFORMATION NO. SI 42NG-023**

**NOTE:** SI's are used only:  
1) To distribute information from DAI to our customers.  
2) To distribute applicable information/documents from our suppliers to our customers with additional information.  
Typically there is no revision service for SI's. Each new information or change of that will be sent along with a new SI.

## **I. TECHNICAL DETAILS**

### **1.1 Airplanes affected:**

All DA 42 NG and DA 42 M-NG airplanes

### **1.2 Subject:**

Installation and tightening torque of worm drive clamps in the charge-air and liquid cooling system.

ATA-Code: 75 and 81

### **1.3 Reason:**

To avoid improper installation and tightening of the worm drive clamps in the charge-air and liquid cooling system.

### **1.4 Information:**

All information previously contained in this Service Information has been incorporated into the AMM with AMM Doc. No. 7.02.15 Revision 2.

## **II. OTHERS**

In case of doubt contact Diamond Aircraft Industries. (mail to: support@diamond-air.at)