

# TEMPORARY REVISION

## AMM-TR-OÄM 42-280

### Cooling - Baffle for Cold Weather Operation

This Temporary Revision AMM-TR-OÄM 42-280 is approved in conjunction with the Optional Design Change Advisory OÄM 42-280/a and is valid in conjunction with the Airplane Maintenance Manual (AMM) until this Temporary Revision has been incorporated into the AMM.

The limitations and information contained herein either supplement or, in the case of conflict, override those in the AMM.

The technical information contained in this document has been approved under the authority of DOA No. EASA.21J.052.

Doc. No.	Section	Affected Pages
7.02.01	05-28-00	3a, 3aa, 10a, 10aa

#### Instruction

- Print this document double-sided on yellow paper (odd pages and "a" pages on front sides, even pages and "aa" pages on reverse sides).
- Insert this cover page as the first page of the AMM.
- Insert the other pages of this Temporary Revision in front of the corresponding AMM pages.

Intentionally left blank

**AFFECTED CHAPTERS:**

**CHAPTER 05**  
**TIME LIMITS AND MAINTENANCE CHECKS**

**Section 05-28-00**  
**Maintenance Checklist DA 42 Engines**

**4. Maintenance Checklist Engines**

**A. LH Engine**

*The following row is added to the existing table:*

		Interval					
	Inspection Items, LH Engine	100	200	1000	2000	Time	Initials
1A.	If OÄM 42-280 is installed:  Examine the Cooling bracket for improper mounting and damage.	X	X	X	X		

Intentionally left blank

**B. RH Engine**

*The following row is added to the existing table:*

		Interval					
	Inspection Items, RH Engine	100	200	1000	2000	Time	Initials
1A.	If OÄM 42-280 is installed:  Examine the Cooling bracket for improper mounting and damage.	X	X	X	X		

Intentionally left blank