

Diamond Aircraft Industries G.m.b.H. N.A. Otto-Straße 5 A-2700 Wiener Neustadt

DAI SI 42-009

Page 1 of 2 07-Jul-2005

FT

SERVICE INFORMATION NO. SI 42-009

NOTE: SI's are used **only**:

1) To distribute information from DAI to our customers.

2) To distribute applicable information / documents from our suppliers to our customers with additional information

Typically there is no revision service for Si's. Each new information or change of that will be send along with a new SI.

I. TECHNICAL DETAILS

1.1 Airplanes affected:

all DA 42

1.2 Subject:

Engine

ATA-Code: 72-00

1.3 Reason:

New TAE Operation & Maintenance Manual TAE 125-01 Doc. No. OM-02-01 Version 3/0.

1.4 Approval:

The technical information contained in this document has been approved under the authority of EASA Design Organization Approval No. EASA.21J.052.



Diamond Aircraft Industries G.m.b.H. N.A. Otto-Straße 5 A-2700 Wiener Neustadt

DAI SI 42-009

Page 2 of 2 07-Jul-2005

FT

1.5 Information:

This SI is issued to ensure that all Diamond Aircraft DA 42 customers take notice of the new issue of the TAE Operation & Maintenance Manual issued on 04.05.2005 and the changes in Section 6.2 Maintenance actions based on operating hours.

The TAE Operation & Maintenance Manual TAE 125-01 Doc. No. OM-02-01 Version 3/0 is applicable with no restriction.

II. OTHERS

In case of doubt contact Diamond Aircraft Industries or Thielert Aircraft Engines GmbH.