

SERVICE INFORMATION NO. SI 42-012

NOTE: SI's are used **only**:

- 1) To distribute information from DAI to our customers.
- 2) To distribute applicable information / documents from our suppliers to our customers with additional information.

Typically there is no revision service for SI's. Each new information or change of that will be send along with a new SI.

I. TECHNICAL DETAILS

1.1 Airplanes affected:

DA 42 - Type

1.2 Subject:

Thielert TM TAE 125-00007
ATA-Code: 71

1.3 Reason:

Thielert issued a statement that the exchange of coolant every 50 hours stipulated in TM TAE 125-0007 is not applicable for the DA 42.

1.4 Information:

Thielert issued a statement that the exchange of coolant every 50 hours stipulated in TM TAE 125-0007 is not applicable for the DA 42, since the DA 42 uses a different cooler than the DA 40 D.

Coolant exchange intervals stated in the Thielert Operation & Maintenance Manual are not affected from this SI.

II. OTHERS

In case of doubt contact Diamond Aircraft Industries.