

## SERVICE INFORMATION NO. SI 42-071

**NOTE:** SI's are used **only**.  
1) To distribute information from DAI to our customers.  
2) To distribute applicable information / documents from our suppliers to our customers with additional information.  
Typically there is no revision service for SI's. Each new information or change of that will be send along with a new SI.

### I. TECHNICAL DETAILS

#### 1.1 Airplanes affected:

All DA 42

#### 1.2 Subject:

ECU Test  
ATA-Code: 76-00

#### 1.3 Reason:

In two cases an engine shutdown has been observed after the ECU Test has been activated with simultaneous application of engine power.

#### 1.4 Information:

Diamond Aircraft draws the attention to the necessity of strictly following the procedures published in the Airplane Flight Manual in particular regarding the FADEC Test sequence.

It is not permitted to initiate the FADEC Test sequence other than as specified in the Airplane Flight Manual Section 4A.6.6, Before Take-Off.

If not complying with this procedure engine stoppage may occur.

### II. OTHERS

In case of doubt contact Diamond Aircraft Industries GmbH.