

SERVICE INFORMATION NO. SI 42-078/1

SUPERSEDES SERVICE INFORMATION No. SI 42-078

NOTE: SI's are used only:

- 1) To distribute information from DAI to our customers.
 - 2) To distribute applicable information/documents from our suppliers to our customers with additional information.
- Typically there is no revision service for SI's. Each new information or change of that will be sent along with a new SI.

I. TECHNICAL DETAILS

1.1 Airplanes affected:

All DA 42 airplanes and
all DA 42 M airplanes
equipped with Honeywell KAP 140 A/P System

1.2 Subject:

Honeywell Service Bulletin KAP 140-22-102
ATA-Code: 22-10

1.3 Reason:

Honeywell has issued a Service Bulletin which addresses possible intermittent operation of the KAP 140 flight control system caused by a bad top cover of the KAP 140.

1.4 Information:

For detailed information please contact your Honeywell Service Center.

II. OTHERS

In case of doubt contact Honeywell International Inc.