

SERVICE INFORMATION NO. SI-42-127

NOTE: SI's are used only:
1) To distribute information from DAI to our customers.
2) To distribute applicable information/documents from our suppliers to our customers with additional information.
Typically there is no revision service for SI's. Each new information or change of that will be sent along with a new SI.

I. TECHNICAL DETAILS

1.1 Airplanes affected:

All DA 42 and DA 42 M aircraft

1.2 Subject:

Airplane Maintenance Manual Chapter 12-30: Conservation of Exterior Parts
ATA-Code: 12-00

1.3 Reason:

Diamond Aircraft Industries GmbH has developed measures against excessive corrosion on exterior parts. These measures are incorporated into the AMM via AMM-TR-MÄM-42-368, which contains detailed information on when and how a new anti-corrosion coating must be applied. To keep the aircraft in good condition and maintenance cost at a minimum, it is very important to follow the instructions published in the AMM.

1.4 Information:

For detailed technical information refer to AMM-TR-MÄM-42-368, which is applicable without any further additions or restrictions.

II. OTHERS

The AMM-TR-MÄM-42-368 is available on the DAI webpage www.diamond-air.at .

In case of doubt contact Diamond Aircraft Industries GmbH.