

# OPTIONAL SERVICE BULLETIN

## OSB 62-007

### **I TECHNICAL DETAILS**

#### **I.1 Category**

Optional.

#### **I.2 Airplanes affected**

Type: DA 62  
Serial numbers: 62.007, 62.009 through 62.015,  
62.017, 62.019 through 62.021,  
62.023, 62.025 through 62.028,  
62.030 through 62.033,  
62.034 and subsequent.

#### **I.3 Date of effectivity**

31-Jan-2017

#### **I.4 Time of Compliance**

At owner's discretion

#### **I.5 Subject**

Retrofit Installation of Tablet Mount on A-Column.

ATA-Code: 25-00

#### **I.6 Reason**

The installation of a standard mounting basis for a tablet holder has been approved for the DA 62. This enhances the comfort while using such a device considerably. This Service Bulletin describes the retrofit installation for airplanes already in service.

#### **I.7 Concurrent Documents**

None.

#### **I.8 Approval**

The technical information or instructions contained in this document relate to the Design Change Advisory No. OÄM 62-033, which has been approved under the authority of EASA Design Organization Approval ref. EASA.21J.052.

The technical content of this document has been approved under the authority of DOA ref. EASA.21J.052.

**I.9 Accomplishments / Instructions**

See WI-OSB 62-007, latest effective issue.

**I.10 Mass (Weight) and CG**

Mass (Weight) and CG not affected.

**II PLANNING INFORMATION****II.1 Material and Availability**

See WI-OSB 62-007, latest effective issue.

**II.2 Special Tools**

None.

**II.3 Labour Effort**

Approx. 8 hours for Serial numbers: 62.007, 62.009 through 62.015, 62.017, 62.019 through 62.021, 62.023, 62.025 through 62.028, 62.030 through 62.033.

Approx. 4 hours for Serial number 62.034 and subsequent

**II.4 Credit**

None.

**II.5 Reference Documents**

DA 62 Airplane Maintenance Manual, Doc. No. 7.02.25, latest effective issue.

**III REMARKS**

1. All work must be done by a certified aircraft service station or a certified aircraft maintenance mechanic.
2. All work, particular that which is not especially described in this Service Bulletin, must be done in accordance with the referenced Maintenance Manual.
3. Completion of all work must be recorded in the log book.
4. In case of doubt contact Diamond Aircraft Industries GmbH.

## EXECUTION REPORT TO SERVICE BULLETIN OSB 62-007

### AIRPLANE INFORMATION

Airplane Serial Number \_\_\_\_\_

Airplane Registration \_\_\_\_\_

Airplane Operator \_\_\_\_\_

Hours of operation of airplane \_\_\_\_\_

No. of landings \_\_\_\_\_

Hours of operation-engine LH \_\_\_\_\_

RH \_\_\_\_\_

Typical operation of airplane private, club, training, other \_\_\_\_\_

\_\_\_\_\_  
Date, Name, Sign

Please fax the completed form to Fax No. +43-2622-26780 or e-mail to  
executionreports@diamond-air.at