

MANDATORY SERVICE BULLETIN NO. MSB 62-036 REV. 2
SUPERSEDES MSB 62-036 REV. 1

I TECHNICAL DETAILS

I.1 Category

Mandatory.

I.2 Airplanes Affected

Type: DA 62

S/N: All

I.3 Date of Effectivity

24 August 2020

I.4 Time of Compliance

At next scheduled maintenance action.

I.5 Subject

Use of AFM Doc. No. 11.01.05-E.

I.6 Reason

The type design responsibility of the DA 62 model was transferred to Diamond Aircraft Industries Inc. (Canada) with the state of design responsibility transferred from EASA to Transport Canada Civil Aviation. As a result of this transfer the aircraft flight manual (AFM) has been reissued under a new document number. This AFM is a revision of the original AFM, 7.01.25-E, and includes all supplements. The new AFM document number is 11.01.05-E and is now the approved AFM for the DA 62 model. The 7.01.25-E AFM will no longer be revised.

I.7 Concurrent Documents

None.

I.8 Approval

The technical content of this document is approved as part of the type design.

I.9 Accomplishment/Instructions

1. Remove AFM 7.01.25-E and its supplements from the aircraft.
2. Install AFM 11.01.05-E and its supplements into the aircraft.
3. Record the completion of this service bulletin in the technical logs of the aircraft.

Diamond Aircraft Industries
MANDATORY SERVICE BULLETIN
Model DA 62



I.10 Mass (Weight) and CG

Not applicable.

II PLANNING INFORMATION

II.1 Material and Availability

DA 62 Airplane Flight Manual Doc. No. 11.01.05-E, latest effective revision, and supplements to AFM 11.01.05-E, latest effective revisions.

II.2 Special Tools

None.

II.3 Labour Effort

Not applicable.

II.4 Credit

Not applicable.

II.5 Reference Documents

None.

III REMARKS

1. Completion of all work must be recorded in the logbook.
2. In case of doubt, contact Diamond Aircraft Industries.

To obtain satisfactory results, procedures specified in this service bulletin must be accomplished in accordance with accepted methods and current government regulations. Diamond Aircraft cannot be responsible for the quality of work performed in accomplishing the requirements of this service bulletin. Diamond Aircraft reserves the right to void continued warranty coverage in the area affected by this service bulletin if it is not incorporated.

If you no longer own the aircraft to which this service bulletin applies, please forward it to the current owner, and send the name of the current owner to Diamond Aircraft at the address below.

Diamond Aircraft Industries Inc.
1560 Crumlin Sideroad, London, Ontario, Canada
N5V 1S2

Customer Support:
Phone: (519) 457-4041, Fax: (519) 457-4045
E-mail: support-canada@diamondaircraft.com

Technical Publications:
E-mail: Techpubs@diamondaircraft.com