

Model DA 62

## **OPTIONAL SERVICE BULLETIN NO. OSB 62-039 REV. 0**

## I TECHNICAL DETAILS

I.1 Category

Optional.

## I.2 Airplanes Affected

Model: DA 62

S/N: All with recirculating air cabin cooling (RACC) system (OÄM 62-005) installed.

## I.3 Date of Effectivity

24 November 2022

## I.4 Time of Compliance

At the owner's discretion.

## I.5 Subject

Installation of an updated ELT bracket.

## I.6 Reason

To improve access to service the ELT battery on all DA 62 aircraft equipped with the recirculating Air cabin cooling (RACC) system (OÄM 62-005), the ELT bracket has been updated. This service bulletin describes the installation of the updated ELT bracket.

## I.7 Concurrent Documents

None.

## I.8 Approval

The technical information and instructions contained in this document relate to Design Change Advisory No. MÄM 62-1104, which has been approved as part of the type design.

## I.9 Accomplishment/Instructions

Comply with WI-OSB 62-039, latest effective issue.

## I.10 Mass (Weight) and CG

The change in mass and CG is negligible.

# Diamond Aircraft Industries OPTIONAL SERVICE BULLETIN



## Model DA 62

## II PLANNING INFORMATION

## II.1 Material and Availability

See WI-OSB 62-039, latest effective issue.

## II.2 Special Tools

None.

## II.3 Labour Effort

Approximately 5 hours will be required to accomplish this service bulletin.

This estimate is for direct labour performed by a technician, and it does not include setup, planning, familiarization, cure time, part fabrication, or tool acquisition.

## II.4 Credit

None.

## II.5 Reference Documents

DA 62 Series Airplane Maintenance Manual, Doc. No. 7.02.25, latest effective issue.

## III REMARKS

- 1. All work must be done by a certified aircraft service station or a certified aircraft maintenance mechanic.
- 2. All work, in particular which is not especially described in this service bulletin, must be done in accordance with the referenced maintenance manual.
- 3. Completion of all work must be recorded in the logbook.
- 4. In case of doubt, contact Diamond Aircraft Industries Inc.



# EXECUTION REPORT TO SERVICE BULLETIN OSB 62-039 REV. 0

## **AIRPLANE DATA**

Airplane serial number			
Airplane registration			
Airplane operator			
Hours of operation of airplane (TSN)			
Typical operation of airplane	private, club, training, other:		
M Date of maintenance	AINTENANCE DATA		
Maintenance carried out by			
During scheduled inspection?	Yes 🗖	No 🔲	
Name	Signature		Date

Please e-mail the completed form to Techpubs@diamondaircraft.com.