Diamond Aircraft Industries Inc.

SERVICE INFORMATION LETTER



SERVICE INFORMATION LETTER NO. SI62-013

NOTE: Service Information Letters are used only:

- 1. To distribute information from Diamond Aircraft Industries Inc. to our customers.
- 2. To distribute applicable information/documents from our suppliers to our customers with additional information.

NOTE: Typically there is no revision service for Service Information Letter (SIL). Each new information or change will be sent along with a new SIL.

1. TECHNICAL DETAILS

1.1 Aircraft Affected

All DA62 aircraft

1.2 Subject

Austro Engine MSB No.MSB-E4-025

ATA-Code: 73-00

1.3 Reason

Cases of premature injector failures have been found by Austro Engine. As the failure of the fuel injectors can lead to loss of compression and subsequent engine failure. Austro Engine has issued MSB-E4-025 which prescribes a time limit for the fuel injectors and provides a time of compliance necessary for safe operation.

1.4 Information

For detailed technical information refer to Austro Engine Mandatory Service Bulletin No. MSB-E4-025 latest revision, which is applicable without any further additions or restrictions.

6

Email: Techpubs @diamondair.com

Diamond Aircraft Industries Inc.

SERVICE INFORMATION LETTER



2. OTHER DETAILS

To obtain satisfactory results, procedures specified in this service information letter must be accomplished in accordance with accepted methods and current government regulations. Diamond Aircraft Industries Inc. cannot be responsible for the quality of work performed in accomplishing the requirements ofthis service information letter. Diamond Aircraft reserves the right to void continued warranty coverage in the area affected by this service information letter if it is not incorporated. If you no longer own the aircraft to which this service information letter applies, please forward it to the current owner and send the name of the current owner to Diamond Aircraft Industries Inc. at the address below.

Diamond Aircraft Industries Inc. 1560 Crumlin Sideroad, London, Ontario, Canada N5V 1S2

Customer Support: Phn: (519)457-4041 Fax:(519)457-4045 Email: customersupport@diamondair.com Technical Publications: Email: techpubs@diamondair.com

Email: Techpubs @diamondair.com

Page 2 of 2 19 October 2018