

## TECHNISCHE MITTEILUNG NR. 20-12

### SERVICE BULLETIN NO. 20-12

Kategorie:

Standard

Betroffene Werknummern:

Alle Werk-Nrn. des Baumusters DV20 "KATANA" von Werk-Nr. 20.005 bis Werk-Nr. 20.069 einschließlich

Gegenstand:

Überprüfen der Kabelschuhbefestigung an der Masseleitung vom Elektronikmodul bei Motor-type 912 Serie

Anlaß:

Siehe Rotax TM 912-06, letztgültige Ausgabe

Maßnahmen:

Siehe Rotax TM 912-06, letztgültige Ausgabe

Dringlichkeit:

Bis spätestens 31. Dezember 1994

Masse und Schwerpunktlage:

Nicht betroffen

Category:

Standard

S/N's affected:

All serial nos. of the model DV 20 "KATANA" from serial no. 20.005 up to serial no. 20.069 incl.

Subject:

Check of the cable bracket attachment of the bonding cable of the electronic modul, engine type 912 series

Reason:

See Rotax SB 912-06, latest edition

Measures:

See Rotax SB 912-06, latest edition

Time of Compliance:

At the latest December 31, 1994

Mass and CG position:

Not affected

Hinweise:

1. Alle Maßnahmen sind vom Flugzeug- oder Motorenhersteller oder von Personen mit entsprechender luftfahrtbehördlicher Berechtigung durchzuführen und im Bordbuch zu bestätigen.
2. Die Rotax TM 912-06 ist Teil dieser TM.

Remarks:

1. All measures must be carried out by the airplane or engine manufacturer or by a certified aircraft maintenance engineer and must be confirmed in the log book.
2. Rotax SB's 912-06 is part of this SB.

Wr. Neustadt, December 14, 1994

ACG approved on

e.h. Dipl.-Ing. (FH) Manfred REICHEL  
Airworthiness

e.h. Ing. Josef EISNECKER  
Dept. 6, Airworthiness