

**VORGESCHRIEBENE TECHNISCHE MITTEILUNG****NR. MSB 20-015/2****ERSETZT TM NR. MSB 20-015/1****MANDATORY SERVICE BULLETIN****NO. MSB 20-015/2****SUPERSEDES MSB 20-015/1****I TECHNISCHE ANGABEN****I.1 Kategorie**

Vorgeschrieben.

**I.2 Betroffene Flugzeuge**DV 20            alle Werknummern  
DV 22            alle Werknummern**I.3 Dringlichkeit**

Nicht anwendbar.

**I.4 Gegenstand**

Revisionsstand des Flughandbuchs.

**I.5 Anlass**

Diese Technische Mitteilung wird durch die aktuellen LOADP Dok. Nr. 4.05.01 Chapter 1 ersetzt.  
Diese Technische Mitteilung wird zurückgezogen.

**I TECHNICAL DETAILS****I.1 Category**

Mandatory.

**I.2 Airplanes affected**DV 20            all serial numbers  
DV 22            all serial numbers**I.3 Time of Compliance**

Not applicable.

**I.4 Subject**

Revision status of Airplane Flight Manual.

**I.5 Reason**

This Service Bulletin is replaced by the current LOADP Doc. No. 4.05.01 Chapter 1.  
This Service Bulletin is revoked.

**I.6 Mitgeltende Unterlagen**

Keine.

**I.7 Genehmigung**

Die technischen Informationen in diesem Dokument sind auf Grundlage des EASA Design Organisation Approval ref. EASA.21J.052 genehmigt worden.

**I.8 Tätigkeiten/Anweisungen**

Keine.

**I.9 Masse und Schwerpunktlage**

Nicht betroffen.

**III HINWEISE**

Im Falle von Unklarheiten, kontaktieren Sie Diamond Aircraft Industries.

**I.6 Concurrent Documents**

None.

**I.7 Approval**

The technical information contained in this document has been approved under the authority of EASA Design Organization Approval ref. EASA.21J.052.

**I.8 Accomplishment/Instructions**

none.

**I.9 Mass (Weight) and CG**

Not affected.

**III REMARKS**

In case of doubt, contact Diamond Aircraft Industries.