

VORGESCHRIEBENE TECHNISCHE MITTEILUNG**NR. MSB 20-045/1****ERSETZT TM MSB 20-045****MANDATORY SERVICE BULLETIN****NO. MSB 20-045/1****SUPERSEDES MSB 20-045****I TECHNISCHE ANGABEN****I.1 Kategorie**

Vorgeschrieben.

I.2 Betroffene Flugzeuge

DV 20 alle Werknummern

I.3 Dringlichkeit

Nicht anwendbar.

I.4 GegenstandRevisionsstand des
Wartungshandbuchs.**I.5 Anlass**

Diese Technische Mitteilung wird durch die aktuellen LOADP Dok. Nr. 4.05.01 Chapter 1 ersetzt.
Diese Technische Mitteilung wird zurückgezogen.

I TECHNICAL DETAILS**I.1 Category**

Mandatory.

I.2 Airplanes affected

DV 20 all serial numbers

I.3 Time of Compliance

Not applicable.

I.4 SubjectRevision status of Airplane
Maintenance Manual.**I.5 Reason**

This Service Bulletin is replaced by the current LOADP Doc. No. 4.05.01 Chapter 1.
This Service Bulletin is revoked.

I.6 Mitgeltende Unterlagen

Keine.

I.7 Genehmigung

Die technischen Informationen in diesem Dokument sind auf Grundlage des EASA Design Organisation Approval ref. EASA.21J.052 genehmigt worden.

I.8 Tätigkeiten/Anweisungen

Keine.

I.9 Masse und Schwerpunktlage

Nicht betroffen.

III HINWEISE

Im Falle von Unklarheiten, kontaktieren Sie Diamond Aircraft Industries.

I.6 Concurrent Documents

None.

I.7 Approval

The technical information contained in this document has been approved under the authority of EASA Design Organization Approval ref. EASA.21J.052.

I.8 Accomplishment/Instructions

none.

I.9 Mass (Weight) and CG

Not affected.

III REMARKS

In case of doubt, contact Diamond Aircraft Industries.