

TECHNISCHE INFORMATION NR. SI20-002

SERVICE INFORMATION NO. SI20-002

I. TECHNISCHE ANGABEN

1.1 Betroffene Flugzeuge

DV 20, DV 22

mit Motor-Werknummern gemäß Rotax
SB-912-022, SB-914-011

1.2 Gegenstand

ATA-Code: 72-30

Ventilfederteller

1.3 Anlaß

Siehe Rotax SB-912-022, SB-914-011.

1.4 Information

Siehe Rotax SB-912-022, SB-914-011.

II. SONSTIGES

Rotax SB-912-022, SB-914-011 ist dieser
Technischen Information beigefügt.

Teilebestellungen und Anträge auf
Rückvergütung sind direkt an den
nächstgelegenen Rotax-Generalvertreter bzw.
Rotax-Service-Stützpunkt zu richten (siehe
Anlage).

I. TECHNICAL DETAILS

1.1 Airplanes affected

DV 20, DV 22

with engine serial numbers according to Rotax
SB-912-022, SB-914-011

1.2 Subject

ATA-Code: 72-30

Valve spring retainer

1.3 Reason

See Rotax SB-912-022, SB-914-011.

1.4 Information

See Rotax SB-912-022, SB-914-011.

II. OTHER INFORMATION

Rotax SB-912-022, SB-914-011 is attached to
this Service Information.

Orders of spare parts and applications for
reimbursement should be addressed directly
to the nearest Rotax General Agent or Rotax
Service Station (see attachment).