

%
%
%



%
%
%
%

TECHNISCHE INFORMATION NR. SI20-003/1
ERSETZT SI20-003
SERVICE INFORMATION NO. SI20-003/1
SUPERSEDES SI20-003

I. TECHNISCHE ANGABEN

1.1 Betroffene Flugzeuge

DV 20
DV 22

mit Motor-Werknummern gemäß

Rotax SB-912-028 & SB-914-016
Rotax SB-914-017
Rotax SB-912-029 & SB-914-018

%
%

jeweilige Ausgabe:
siehe II. SONSTIGES

1.2 Gegenstand

ATA-Code: 71-20
Motorträger
ATA-Code: 78-10
Einströmrohre
ATA-Code: 72-20
Kurbelgehäuse

1.3 Anlaß

Siehe Rotax SB-912-028 & SB-914-016
Rotax SB-914-017
Rotax SB-912-029 & SB-914-018

%
%

jeweilige Ausgabe:
siehe II. SONSTIGES

I. TECHNICAL DETAILS

1.1 Airplanes affected

DV 20
DV 22

with engine serial numbers according to

Rotax SB-912-028 & SB-914-016
Rotax SB-914-017
Rotax SB-912-029 & SB-914-018

respective issue:
see II. OTHER INFORMATION

1.2 Subject

ATA-Code: 71-20
Engine Mount
ATA-Code: 78-10
Exhaust bends
ATA-Code: 72-20
Crankcase

1.3 Reason

See Rotax SB-912-028 & SB-914-016
Rotax SB-914-017
Rotax SB-912-029 & SB-914-018

respective issue:
see II. OTHER INFORMATION

%
%
%



Diamond Aircraft Industries GmbH
N.A. Otto-Straße 5
A-2700 Wiener Neustadt, Austria

DAI SI20-003/1
Page 2 of 2
03-Jan-2002

1.4 Information

Siehe Rotax SB-912-028 & SB-914-016
Rotax SB-914-017
Rotax SB-912-029 & SB-914-018

%
%

jeweilige Ausgabe:
siehe II. SONSTIGES

II. SONSTIGES

%
%
%
%

1. Diese Technische Information wurde neu herausgegeben, weil in Rotax SB-914-018 der Bereich der betroffenen Seriennummern geändert wurde.

2. Dieser Technischen Information sind beigefügt:

%
%
%
%
%
%

Rotax SB-912-028, Erstausgabe
Rotax SB-914-016, Erstausgabe

Rotax SB-914-017, Erstausgabe

Rotax SB-912-029, Erstausgabe
Rotax SB-914-018, Revision 1

3. Teilebestellungen und Anträge auf Rückvergütung sind direkt an den nächstgelegenen Rotax-Generalvertreter bzw. Rotax-Service-Stützpunkt zu richten.

1.4 Information

See Rotax SB-912-028 & SB-914-016
Rotax SB-914-017
Rotax SB-912-029 & SB-914-018

respective issue:
see II. OTHER INFORMATION

II. OTHER INFORMATION

1. This Service Information was re-issued because the serial number range in Rotax SB-914-018 was changed.

2. Attached to this Service Information are:

Rotax SB-912-028, Initial Issue
Rotax SB-914-016, Initial Issue

Rotax SB-914-017, Initial Issue

Rotax SB-912-029, Initial Issue
Rotax SB-914-018, Revision 1

3. Orders of spare parts and applications for reimbursement should be addressed directly to the nearest Rotax General Agent or Rotax Service Station.