

TECHNISCHE INFORMATION NR. SI20-006

SERVICE INFORMATION NO. SI20-006

I. TECHNISCHE ANGABEN

1.1 Betroffene Flugzeuge

DV 20 mit Rotax 912 A-Motor (80 PS):
alle Flugzeuge mit Motor-Werknum-
mern gemäß Rotax SB-912-032

1.2 Gegenstand

ATA-Code: 79-20
Ölpumpe

1.3 Anlaß

Siehe Rotax SB-912-032.

1.4 Information

Siehe Rotax SB-912-032.

II. SONSTIGES

1. Rotax SB-912-032 ist dieser Technischen Information beigelegt.
2. Teilebestellungen und Anträge auf Rückvergütung sind direkt an den nächstgelegenen Rotax-autorisierten Vertriebspartner bzw. Rotax Service Center zu richten (siehe www.rotax-aircraft-engines.com).

I. TECHNICAL DETAILS

1.1 Airplanes affected

DV 20 with Rotax 912 A engine (80 hp):
all airplanes with engine serial num-
bers according to Rotax SB-912-032

1.2 Subject

ATA code: 79-20
Oil pump

1.3 Reason

See Rotax SB-912-032.

1.4 Information

See Rotax SB-912-032.

II. OTHER INFORMATION

1. Rotax SB-912-032 is attached to this Service Information.
2. Orders of spare parts and applications for reimbursement should be addressed directly to the nearest Rotax Authorized Distributor or Rotax Service Center (see www.rotax-aircraft-engines.com).