

# HOFFMANN AIRCRAFT

FLUGZEUGPRODUKTION und ENTWICKLUNG  
Gesellschaft m.b.H.

page 1

(Translation)

No of pages: 1

## Service Bulletin 1E

=====

Affected Aircraft: SNo's of type H 36 DIMONA:

3601, 3602, 3604, 3605, 3609, 3610, 3611

Subject: Throttle control

Occasion: Failure of throttle control of one aircraft.

Required Actions: 1. Unhinge bowden wire and remove throttle control

2. Mount strengthend throttle control according to drawing No. 820.4.39.51 with modification from 1982/8/24.

Hinge bowden wire. Check if both strokes of the throttle rods in the engine compartment are reached.

Urgency: Before next flight.

Weight and balance: not affected.

Remark: Actions 1 and 2 must be performed by a competent person, and must be certified in the logbook.

Hirt, 1982 09 07

BAZ approved on 1982 09 14

Dipl.-Ing. D. Opperl

Baha