

HOFFMANN AIRCRAFT

FLUGZEUGPRODUKTION und ENTWICKLUNG
Gesellschaft m.b.H.

page 1

(Translation)

No of pages: 1

Service Bulletin 4

=====

Affected Aircraft: All "No's of type H 36 DIMONA

Subject: During series production the masses of the control surfaces could be decreased. For that reason new flutter calculations have been performed, which take into account lower masses of the control surfaces and a lower moment of the aileron.

Required actions: The actions were exchanges of pages of the german handbook for continued airworthiness of the year 1982. The data are ofcourse updated now (1986).

Weight and balance: not affected

Hirt, 1982 10 19

BAZ approved on 1982 11 26

Dipl.-Ing. D. Opperl

Baha