

HOFFMANN AIRCRAFT

FLUGZEUGPRODUKTION und ENTWICKLUNG
Gesellschaft m.b.H.

(Translation)

page 1

No of pages: 2

Service Bulletin 12

=====

Affected Aircraft: All SNo's of motorglider
type H 36 DIMOMA

Subject: Spin

Occasion: Due to irregularities observed at spinning the
aircraft, additional tests for spinning will be per-
formed.

Until results are available, the following actions
must be performed:

Required actions: 1. Installation of a placard on a good visible
place on the instrument panel, containing
the following text:

All aerobatic manoevers inclusive
spin are forebidden

2. Exchange of pages of the German flight
manual of the year 1985.

(In the current English manuals the necessary
changes are taken into consideration).

Urgency: Before next flight

Weight and balance: not affected

Remarks: The required actions must be performed by a competent person and must be certified in the log-book.

Further necessary actions will be published by an additional S. B.

Hirt, 1985 01 17

LBA-approved on 1985 01 22

Dipl.-Ing. D. Oppel

Reinke