

SERVICE BULLETIN NO. 36/1

EQUAL TO SB 36, BUT REFERS TO
MANUALS ISSUED MAY 17, 1993
(DOC. # 3.01.21, 3.01.22, 3.02.21)

- S/N's
affected: All HK 36 R "Super Dimona" serial numbers.
- Subject: Use of unleaded fuel.
- Reason: The original fuel hoses are not approved for the use of unleaded fuel. If unleaded fuel (automotive premium grade gasoline, minimum octane rating 95) is to be used, this SB must be carried out.
- Measures:
1. Replacement of fuel hoses; attachment of new placard.

All fuel hoses and the placard next to the tank filler cap showing the list of approved fuel grades must be replaced in accordance with HOAC Work Instruction No. 16.
 2. Flight Manual Revision.
 - (a) Replace pages III and 2-12 with the new pages dated Feb. 14, 1994.

Two versions of page III are supplied. The one that lists page 3-8 is for the Flight Manual Doc. No. 3.01.21, the one that does not is for Doc. No. 3.01.22.
 - (b) Confirm revision on page II.
 3. Maintenance Manual Revision.
 - (a) Replace pages 4.1 and 4.22 with the new pages dated Feb. 14, 1994.
 - (b) Confirm revision on page 0.2.

Time of compliance: This is a recommended SB. It must be carried out prior to using unleaded fuel.

Mass and CG: Not affected.


Remarks: 1. Work Instruction No. 16 is part of this SB.
2. All measures must be carried out by a competent person and confirmed in the logbook.

Wr. Neustadt, April 14, 1994

ACG-approved on June 15, 1994



Dipl.-Ing. Martin Volck
Technical Manager

JA Dundler 

Ing. J. Dundler
Dep. 6 - Airworthiness