

# TECHNISCHE INFORMATION NR. SI36-007

## SERVICE INFORMATION NO. SI36-007

### **I. TECHNISCHE ANGABEN**

#### **1.1 Betroffene Flugzeuge**

alle Flugzeuge der Baureihen

H 36 VT,  
HK 36 R,  
HK 36 TS,  
HK 36 TC

mit Rotax 912 A-Motor (80 PS) mit Motor-  
Werknummern gemäß Rotax SB-912-032

#### **1.2 Gegenstand**

ATA-Code: 79-20  
Ölpumpe

#### **1.3 Anlaß**

Siehe Rotax SB-912-032.

#### **1.4 Information**

Siehe Rotax SB-912-032.

### **II. SONSTIGES**

1. Rotax SB-912-032 ist dieser Technischen Information beigelegt.
2. Teilebestellungen und Anträge auf Rückvergütung sind direkt an den nächstgelegenen Rotax-autorisierten Vertriebspartner bzw. Rotax Service Center zu richten (siehe [www.rotax-aircraft-engines.com](http://www.rotax-aircraft-engines.com)).

### **I. TECHNICAL DETAILS**

#### **1.1 Airplanes affected**

all airplanes of the models

H 36 VT,  
HK 36 R,  
HK 36 TS,  
HK 36 TC

with Rotax 912 A engine (80 hp) with engine  
serial numbers according to Rotax  
SB-912-032

#### **1.2 Subject**

ATA code: 79-20  
Oil pump

#### **1.3 Reason**

See Rotax SB-912-032.

#### **1.4 Information**

See Rotax SB-912-032.

### **II. OTHER INFORMATION**

1. Rotax SB-912-032 is attached to this Service Information.
2. Orders of spare parts and applications for reimbursement should be addressed directly to the nearest Rotax Authorized Distributor or Rotax Service Center (see [www.rotax-aircraft-engines.com](http://www.rotax-aircraft-engines.com)).