

Diamond Aircraft Publications			
Doc. No.	Description	Revision 112 Updates	Status
DA201-C1 AMM-TR-25-10/a	Fuel Line Torques		Rev 1 - Sep-03-25
Diamond Aircraft Publications			
Doc. No.	Description	Full Listing	Status
<u>Aircraft Manuals</u>			
DA200-C1	List of Applicable Publications (this document)		Rev 112 - Sep-16-25
DA201-C1	Aircraft Maintenance Manual		Rev 25- Mar-14-23
DA201-C1 TR-MAM-22-0016	Flap Actuator Motor		Rev 0 - Dec-16-24
DA201-C1 TR-MOD0333	Installation of the Artex ELT 1000		Rev 0 - Jan-15-25
DA201-C1 AMM-TR-25-10/a	Fuel Line Torques		Rev 1 - Sep-03-25
DA201-C1 AMM-TR-MAM-22-0035	Inspection of Flap Bellcrank		Rev 0 - Aug-14-25
DA202-C1	Airplane Flight Manual (English Day/Night VFR)		Rev 29 - Jun-30-21
DA202-C1 TR# 23-01	Amerex 337TS Fire Extinguisher		Rev 0 - Apr-01-23
DA203-C1	Illustrated Parts Catalogue		Rev 12 - Aug-27-21
DA203-C1	Illustrated Parts Catalogue		Rev 13- Apr-17-23

Diamond Aircraft Publications			
Doc. No.	Description	Full Listing	Status
<u>Service Bulletins</u> (A) = Alert, (M) = Mandatory, (O) = Optional, (R) = Recommended			
Chapter 11 - Placards and Markings			
DAC1-11-01 (R)	Chinese Placards and Markings		Rev 3 - Sep-29-14
Chapter 23 - Communications			
DAC1-23-01 (R)	GMA 340 Isolation Diodes		Rev 0 - Dec-08-04
DAC1-23-50 (O)	Installation of 27 Ohm Resistor		Rev 0 - Sep-09-09
Chapter 24 - Electrical Power			
DAC1-24-01 (R)	Generator Lower Attaching Bolt Replacement		Rev 1 - Mar-03-10
DAC1-24-03 (O)	G-35M Battery Option		Rev 2 - Apr-27-10
DAC1-24-04 (R)	Generator Attachment Bracket		Rev 3 - Jul-18-08
DAC1-24-05 (O)	Installation of the BC100-1 or the ODS-AGM28LMJ Battery on the Battery Shelf		Rev 2 - Mar-30-23
DAC1-24-06 (O)	Installation of YTX24HL-BS Battery on Firewall		Rev 0 - Jan-14-04
DAC1-24-07 (O)	Replacement of Battery/EPU Relay Contactor		Rev 0 - Nov-08-12
DAC1-24-08 (O)	Installation of the external power unit (EPU) system		Rev 1 - Jan-23-20
DAC1-24-09 (O)	Installation of the ODS-AGM28LMJ Battery on the Firewall		Rev 1 - Sep-18-23
Chapter 25 - Equipment and Furnishings			
DAC1-25-01 (R)	EBC502 to Artex ELT Upgrade		Rev 6 - Jan-13-25
DAC1-25-02 (R)	ME406 ELT Installation on Reverse Panel		Rev 0 - Nov-23-10
DAC1-25-03 (O)	Installation of Safety Hammer, Type II		Rev 0 - Aug-19-11
DAC1-25-04 (O)	ELT 1000 Retrofit		Rev 1 - Jan-13-25
Chapter 27 - Flight Controls			
DAC1-27-01 (O)	Control Stick Elevator Trim Installation		Rev 0 - Apr-26-01
DAC1-27-02 (O/R)	Flap Actuator Bushing Retainers		Rev 1 - Feb-01-08
DAC1-27-03 (M)	Inspection of Flap Bellcrank (Mandatory)		Rev 1 - May-13-19
DAC1-27-04 (O)	Installation of Diamond Flap Control & Microswitch Tray		Rev 1 - Jan-10-20
DAC1-27-05 (O)	Replacement of the flap actuator and installation of the flap resistor assembly		Rev 1 - Mar-13-25
Chapter 28 - Fuel System			
DAC1-28-01 (O)	Type II Fuel System/Pump Retrofit		Rev 0 - Oct-08-98
DAC1-28-02 (M)	2-Speed Electric Fuel Pump System		Rev 3 - Oct-27-99

Diamond Aircraft Publications			
Doc. No.	Description	Full Listing	Status
Chapter 30 - Ice and Rain Protection			
DAC1-30-02 (O)	Installation of a Heated Pitot Static Probe		Rev 1 - Aug-25-22
Chapter 31 - Indicating Systems			
DAC1-31-01 (O)	Removal of OAT/Clock AA Battery		Rev 0 - Jun-29-17
Chapter 32 - Landing Gear			
DAC1-32-01 (O/R)	Nose Gear Shock Strut		Rev 0 - Feb-28-07
DAC1-32-02 (O)	Optional Installation of Extended Main Landing Gear Struts		Rev 0 - Jun-05-09
DAC1-32-03 (R)	NLG Wheel and Fork Installation Improvements		Rev 0 - Jul-15-11
Chapter 33 - Lights			
DAC1-33-01 (O)	Recognition Lights		Rev 1 - Feb-21-00
DAC1-33-02 (O)	Installation of Replacement Electro Luminescent (EL) Flood Light		Rev 1 - Aug-11-11
DAC1-33-04 (O)	Installation of Backlighting on the Instrument Panel		Rev 2 - Feb-06-12
DAC1-33-05 (R)	Installation of RFI Protected Lighting Voltage Regulator Assembly		Rev 0 - Feb-23-15
DAC1-33-06 (O)	Installation of LED Anti-Collision and Position Light Assembly		Rev 3 - May-13-19
DAC1-33-07 (O)	Installation of Dimming Module		Rev 1 - Jan-10-20
DAC1-33-08 (O)	Installation of LED Landing and Taxi Lights		Rev 0 - Oct-13-22
Chapter 34 - Navigation			
DAC1-34-02 (O)	Installation of Backup Artificial Horizon Indicator		Rev 2 - Jan-28-13
DAC1-34-06 (R)	Garmin G500 Software Upgrade		Rev 0 - Mar-07-14
DAC1-34-09 (O)	Garmin G500 Software Upgrade 006-B1076-63		Rev 0 - Jun-20-16
DAC1-34-10 (M)	GTX345 and TAS605 Audio Lines		Rev 0 - Oct-13-20
DAC1-34-11 (O)	Garmin GI 275 Installation		Rev 0 - May-13-21
DAC1-34-12 (O)	This service bulletin addresses the installation of COMM 2.		Rev 0- Mar-05-24
Chapter 52 - Doors			
DAC1-52-01 (O)	Canopy, Seal Replacement		Rev 0 - Jan-07-99
DAC1-52-03 (R)	Canopy Lock Cover Plate Installation		Rev 1 - Aug-17-99
Chapter 53 - Fuselage			
DAC1-53-01 (R)	Spar Bridge Gusset Reinforcement		Rev 3 - Sep-15-14
Chapter 55 - Stabilizers			
DAC1-55-01A (A)	Horizontal Stabilizer Attachment		Rev 3 - Mar-30-01

Diamond Aircraft Publications			
Doc. No.	Description	Full Listing	Status
Chapter 57 - Wings			
DAC1-57-01 (O)	Installation of Aileron Roller Guide Access Panels		Rev 1 - May-13-19
Chapter 61 - Propellers			
DAC1-61-00A (A)	Spinner Rear Bulkhead Replacement		Rev 1 - Apr-02-01
DAC1-61-01 (R)	Sensenich W69EK7-63 Propeller Installation		Rev 5 - Nov-29-19
Chapter 71 - Power Plant - General			
DAC1-71-01 (O)	Cowling Thermal Protection Shielding		Rev 1 - May-16-02
DAC1-71-02	Engine Mount to Firewall Washers		Rev 0 - Jan-19-04
DAC1-71-03 (O)	Winterization Kit		Rev 0 - May-19-04
DAC1-71-04 (O)	Enlarged Cowl Inlet for Hot Weather Operation		Rev 0 - Jun-29-04
Chapter 73 - Engine Fuel and Controls			
DAC1-73-04 (O/R)	Engine Fuel System Conversion IO-240-B17B to IO-240-B3B		Rev 5 - Nov-26-10
DAC1-73-05 (M)	Operating Limitations with Altitude Compensating Fuel Systems		Rev 1 - Dec-14-07
Chapter 74 - Engine Ignition			
DAC1-74-01 (R)	Ignition Harness Routing		Rev 1 - Sep-19-14
DAC1-74-02 (R)	Starting Vibrator Battery Installation		Rev 0 - Feb-18-00
DAC1-74-03 (O)	Installation of Optional Push-to-Start Ignition Switch		Rev 2 - Mar-09-11
DAC1-74-04 (O)	Installation of the Yuasa NP1.2-12 starter vibrator battery and battery tray		Rev 0 - Sep-01-22
Chapter 76 - Engine Controls			
DAC1-76-01 (R)	Mixture Cable Kinking		Rev 1 - Jan-29-99
DAC1-76-02 (R)	Mixture Cable Routing - Reversed Panel		Rev 0 - Dec-03-03
DAC1-76-03 (O)	Installation of Mixture Cable for Altitude Compensating Fuel Pump		Rev 2 - Mar-06-06
DAC1-76-04 (R)	Throttle Cable Firewall Feed-Thru		Rev 1 - Jan-28-10
Chapter 77 - Engine Indicating			
DAC1-77-01 (O)	Installation of Improved Indicating Systems		Rev 5 - Feb-09-23
Chapter 79 - Engine Oil System			
DAC1-79-01 (O)	Power Plant Cooling		Rev 0 - Nov-09-99
DAC1-79-02 (R)	Oil Filler Bracket Installation		Rev 0 - Apr-10-01

DA20-C1

List of Applicable Publications

Diamond Aircraft Publications			
Doc. No.	Description	Full Listing	Status
Miscellaneous			
DAC1-92-03	Mexican Import Requirements		Rev 0 - Feb-28-07
DAC1-92-07	Operation Limit Changes for EASA Member Countries		Rev 1 - Aug-09-12
DAC1-92-08	Installation of Illuminated Placards		Rev 0 - Aug-09-12
<u>Service Information Letters</u>			
SIL20C1-001	Service Information Letter to introduce Garmin Software Service Bulletin No.: 0943 Rev A.		Rev 0 - Jan-11-10
SIL20C1-002	Service Information Letter to introduce Garmin Service Bulletin No. 0714 Rev. A.		Rev 0 - Mar-24-10
SIL20C1-003	Service Information Letter to introduce AMM TR # 12-01, Scheduled Servicing for Brake Pedal Pivot		Rev 0 - May-12-10
SIL20C1-004	Service Information Letter to introduce application of wheel bearing grease for wheel assemblies		Rev 0 - Aug-03-10
SIL20C1-005	Service Information Letter to introduce new improved design of NLG fork assembly		Rev 0 - Oct-07-10
SIL20C1-006	Service Information Letter for the inspection and maintenance of the throttle control arms installation		Rev 0 - Jan-22-13
SIL20C1-007	Service Information Letter to introduce Garmin Service Advisory No. 1361		Rev 0 - Nov-20-13
SIL20C1-008	Service Information Letter to introduce Andiar Service Alert GAS375-D		Rev 0 - Jan-22-13
SIL20C1-009	Service Information Letter to introduce Slick Service Bulletin SB1-15A		Rev 1 - Jan-10-19
SIL20C1-010	Service Information Letter to introduce United Instruments Service Bulletin No.13		Rev 0 - Apr-14-16
SIL20C1-011	Service Information Letter regarding LPI of the NLG Strut		Rev 0 - Sep-19-18
SIL20C1-012	Inspection of aircraft step assemblies		Rev 0 - May-07-19
SIL20C1-013	Aircraft cleaning and disinfection recommendations		Rev 0 - May-21-20
SIL20C1-014	Nose landing gear maintenance and inspections		Rev 0 - Jan-12-23
SIL20C1-015	Garmin SB22071		Rev 0 - Aug-10-22
SIL20C1-016	United Instruments Service Note No. 14		Rev 0 - Apr-13-23

Continental Motors Publications

For the complete and up-to-date list of Continental Motors publications, refer to their website:

<http://www.genuinecontinental.aero/PublicationList.aspx>

Hoffmann Propeller Publications

For the complete and up-to-date list of Hoffmann Propeller publications, refer to their website:

<http://www.hoffmann-prop.com/en/index.php>

Sensenich Propeller Publications

For the complete and up-to-date list of Sensenich Propeller publications, refer to their website:

<http://www.sensenich.com/support/documents>



DA20-C1 List of Applicable Publications

This list identifies documentation directly applicable to the safe operation and maintenance of the DA20-C1 aircraft. It is recommended that operators periodically verify that their documentation is at the correct issue/revision levels. The List of Applicable Publications (LOAP) will be updated at least quarterly, and sent to all registered subscribers. If you have not received your LOAP update for more than three months, contact Diamond Aircraft Customer Support at the following listed numbers immediately.

This list includes links to relevant vendor documents that Diamond Aircraft is aware of for the DA20-C1 aircraft. Vendor documents are not posted on the Diamond Aircraft website.

Other information pertaining to specific components (e.g. avionics) should be obtained directly from the vendor or manufacturer.

For publication revision and subscription service, please contact the following:

Diamond Aircraft Industries	
North America, Australia, South Africa: Diamond Aircraft Industries Inc. Customer Support 1560 Crumlin Sideroad London, ON, Canada N5V 1S2 Phone: 519-457-4041	Europe, Other: Diamond Aircraft Industries GmbH. Customer Support N.A. Otto-Strasse 5 A-2700 Wiener Neustadt Austria Phone: 011-43-2622-26700
Teledyne Continental Motors	
Contact TCM directly for publication information. North America: Teledyne Continental Motors P.O. Box 90 Mobile, Alabama, USA 36601 Phone: 334-438-3411	
Sensenich Propeller Manufacturing Company	
Contact Sensenich directly for publication information. North America: Sensenich Wood Propeller Company 2008 Wood Court Plant City, Florida 33567 Phone: 813-752-3711	
Hoffmann Propeller	
North America, Australia, South Africa: Authorized Distributor Diamond Aircraft Industries Inc. Customer Support 1560 Crumlin Sideroad London, ON, Canada N5V 1S2 Phone: 519-457-4041	Europe, Other: Hoffmann Propeller GmbH. & Co. Customer Support Kupferlingstr. 9 D-83022 Rosenheim Germany Phone: 011-49-8031-1878-0