

SERVICE INFORMATION LETTER



Page: 1 of 1
20 Nov 13

SERVICE INFORMATION LETTER NO. SIL20C1-007

NOTE: Service Information Letters are used only:

1. To distribute information from Diamond Aircraft Industries (DAI) to our customers.
2. To distribute applicable information/documents from our suppliers to our customers with additional information.

NOTE: Typically there is no revision service for Service Information Letter (SIL). Each new information or change will be sent along with a new SIL.

1. TECHNICAL DETAILS

1.1 Aircraft Affected

All DA20-C1 aircraft with Garmin G500 Avionics.

1.2 Subject

Garmin Service Advisory No. 1361, Possible Temporary loss of heading/attitude information in Garmin G500 and G600 Systems following extended power-on stall and slow flight maneuvers.

1.3 Reason

Temporary loss of heading information may be lost during some in flight operations at sustained slow speeds

1.4 Information

For detail information refer to Garmin Service Advisory No. 1361

2. OTHERS

Contact DAI, your local authorized Diamond Service Center or Garmin if more information is required.

To obtain satisfactory results, procedures specified in this service information letter must be accomplished in accordance with accepted methods and current government regulations. Diamond Aircraft Industries Inc. cannot be responsible for the quality of work performed in accomplishing the requirements of this service information letter. Diamond Aircraft reserves the right to void continued warranty coverage in the area affected by this service information letter if it is not incorporated. If you no longer own the aircraft to which this service information letter applies, please forward it to the current owner and send the name of the current owner to Diamond Aircraft Industries Inc. at the address below.

Diamond Aircraft Industries Inc. 1560 Crumlin Sideroad, London, Ontario, Canada N5V 1S2

Customer Support: Phone: (519) 457-4041 Fax: (519) 457-4045 E-mail: custsupp@diamondair.com
Technical Publications: Phone: (519) 457-4030 Ext. 3173 E-mail: techpubs@diamondair.com