

# SERVICE INFORMATION LETTER



Page: 1 of 1  
22 Jan 13

## SERVICE INFORMATION LETTER NO. SIL20C1-008

NOTE: Service Information Letters are used only:

1. To distribute information from Diamond Aircraft Industries (DAI) to our customers.
2. To distribute applicable information/documents from our suppliers to our customers with additional information.

NOTE: Typically there is no revision service for Service Information Letter (SIL). Each new information or change will be sent along with a new SIL.

### 1. TECHNICAL DETAILS

#### 1.1 Aircraft Affected

All DA20-C1 aircraft with a Continental Motors IO-240B engine.

#### 1.2 Subject

Andair GA375-D Gascolator Filters  
ATA-Code: 71-00

#### 1.3 Reason

Andair Ltd. has issued a service alert regarding the GAS375-D gascolators. Some gascolators have been fitted with a filter that is not properly marked. Some of the FIA375 filters did not have the -10M suffix added to the part mark. The filter is the correct mesh size it was not properly marked.

#### 1.4 Information

For detailed information refer to the Andair Ltd. service alert. This is attached.

### 2. OTHERS

Contact DAI or your local authorized Diamond Service Center if more information is required.

To obtain satisfactory results, procedures specified in this service information letter must be accomplished in accordance with accepted methods and current government regulations. Diamond Aircraft Industries Inc. cannot be responsible for the quality of work performed in accomplishing the requirements of this service information letter. Diamond Aircraft reserves the right to void continued warranty coverage in the area affected by this service information letter if it is not incorporated. If you no longer own the aircraft to which this service information letter applies, please forward it to the current owner and send the name of the current owner to Diamond Aircraft Industries Inc. at the address below.

Diamond Aircraft Industries Inc. 1560 Crumlin Sideroad, London, Ontario, Canada N5V 1S2

Customer Support: Phone: (519) 457-4041 Fax: (519) 457-4045 E-mail: [custsupp@diamondair.com](mailto:custsupp@diamondair.com)  
Technical Publications: Phone: (519) 457-4030 Ext. 3173 E-mail: [techpubs@diamondair.com](mailto:techpubs@diamondair.com)

## SERVICE ALERT

Andair Ltd.,  
Unit 1,  
Dunsbury Business Park,  
Fullood Road,  
Havant,  
Hampshire,  
PO9 5AX,  
UK.

1st Issued February 2014

### GAS375 Filters SERVICE ALERT

This Service Alert only applies to Andair Gascolators that have been supplied with 10 micron filters.

It has come to our attention that some filters for the GAS375 Gascolators have been fitted with filters with the incorrect part number on them. The filters in question are part numbers FIA375-10M, but the -10M suffix has been omitted.

It should be noted that the filters do have the correct mesh fitted, and will function correctly, but the incorrect part number marked on them could lead to someone ordering an incorrect replacement.

If you have a GAS375 Gascolator that was supplied with a 10 micron filter then at the next service interval, please check, or get it checked for you, that the the correct part number is shown. If it is found that the part number is incorrect then either amend it by carefully hand engraving the -10M suffix, or return it to us at the above address and we will do this for you.

This SA will be issued to all customers that our records show have had GAS375 gascolators with 10 micron and will be displayed on our web site

[www.andair.co.uk](http://www.andair.co.uk)  
contact e-mail: [andair@andair.co.uk](mailto:andair@andair.co.uk)  
Telephone No: +44 (0) 2392 473945  
Fax No: +44(0) 2392 473946