

SUPPLEMENTAL AIRPLANE MAINTENANCE MANUAL

Flap Actuator with Changed Motor

This Supplemental AMM is approved in conjunction with the DEO valid in conjunction with the basic Airplane Maintenance Manual (AMM).

The limitations and information contained herein either supplement or, in the case of conflict, override those in the AMM.

Doc. No. : 6.02.15 - DEO 40-015

Date of Issue : 07-May-2024

Design Change Advisory : DEO 40-015

This document must be carried in the Airplane Maintenance Manual (AMM) at all times. It describes the maintenance procedures.

The technical content of this document has been approved under the authority of the DOA ref. EASA.21J.052.

Intentionally left blank.

RECORD OF REVISIONS

Rev. No.	Reason	Chapter	Page(s)	Date of Revision	Approval Note	Date of Approval	Date Inserted	Signature

Intentionally left blank.

TABLE OF CONTENTS

CHAPTER 03 – GENERAL DESCRIPTION..... 1
 2. Description..... 1

CHAPTER 92 – WIRING DIAGRAMS..... 1
 1. General..... 1

Intentionally left blank.

FOREWORD

This document is protected by copyright. All associated rights, in particular those of translation, reprinting, radio transmission, reproduction by photo-mechanical or similar means and storing in data processing facilities, in whole or part, are reserved.

Copyright © by: DIAMOND AIRCRAFT INDUSTRIES GMBH
Nikolaus-August-Otto-Strasse 5
2700 Wiener Neustadt, Austria
Phone : +43-2622-26700
Fax : +43-2622-26780
E-Mail : office@diamondaircraft.com

Any occurrence related to this DEO shall be reported in writing to the address above or submitted to
E-Mail: airworthiness-austria@diamondaircraft.com

Intentionally left blank.

CHAPTER 03 – GENERAL DESCRIPTION

2. Description

A new flap actuator is replacing the previous model for obsolescence reasons. The new flap actuator (EA4-2753-10-00_01_EPA) requires a new flap resistor assembly (EA4-2753-00-90_01_EPA) and a new mounting bracket (EA4-2750-00-01_EPA) to install the flap actuator to the fuselage.

Intentionally left blank.

CHAPTER 92 – WIRING DIAGRAMS

1. General

Title	Drawing Number	Revision Number	Number of Sheets
Schematic, Flaps Wiring	E44-9227-50-01_01	-	1

Intentionally left blank

F

F

E

E

D

D

C

C


B

B

A

A

ALL RIGHTS RESERVED FOR THIS DOCUMENT WHICH MAY NOT BE REPRODUCED OR DISCLOSED TO THIRD PARTIES WITHOUT THE PRIOR WRITTEN CONSENT OF DIAMOND AIRCRAFT INDUSTRIES



DIMENSIONS METRIC FIRST ANGLE PROJECTION 		IDENTIFICATION MARKINGS DP-S-17-00001 CLASSIFICATION: NONE INTERCHANGEABLE PART NO THIS DRAWING WAS PRODUCED USING SOFTWARE: SOLID EDGE FILENAME E44-9227-50-01-01.dft		Diamond Aircraft Industries N. A. Otto-Straße 5 A-2700 Wiener Neustadt		PROJECT DA 40 NG TITLE SCHEMATIC FLAPS WIRING DWG.ORIG. DAIA DWG.NO. E44-9227-50-01_01 REV - CODE 710197 SCALE SH 01 OF 01	
IF NOT OTHERWISE SPECIFIED GEOMETRIC DIMENSIONING AND TOLERANCING ACC. TO ISO 2768-mK DIMENSIONS IN mm		FINISH IN MICROMETER 		NAME / SIGN / DATE DRAWN: CHECKED: RELEASED:			