

## Diamond Aircraft Industries GmbH N. A. Otto-Straße 5 2700 Wiener Neustadt Austria

DAI OSB 40NG-035 Page 1 of 3 02-Dec-2014

# OPTIONAL SERVICE BULLETIN OSB 40NG-035

# I <u>TECHNICAL DETAILS</u>

#### I.1 Category

Optional.

# I.2 Airplanes affected

Type: DA 40 NG

Serial numbers: 40.N001 and subsequent

Only airplanes with Large Tires (OÄM 40-334) installed

# I.3 Date of effectivity

02-Dec-2014

#### I.4 Time of Compliance

At owner's discretion

#### I.5 Subject

Installation of a hydraulic NLG damper.

ATA-Code: 32-20

### I.6 Reason

For improved ground comfort a hydraulic nose landing gear damper has been developed. This Service Bulletin describes the installation for airplanes already in service.

# I.7 Concurrent Documents

None.

#### I.8 Approval

The technical information or instructions contained in this document relate to the Design Change Advisory No. OÄM 40-379, which has been approved under the authority of EASA Design Organization Approval ref. EASA.21J.052.

The technical content of this document has been approved under the authority of DOA ref. EASA.21J.052.

#### I.9 Accomplishments / Instructions

See WI-OSB 40NG-035, latest effective issue.

#### I.10 Mass (Weight) and CG

Weight increase approx. 2 kg.

# Diamond Aircraft Industries GmbH N. A. Otto-Straße 5 2700 Wiener Neustadt Austria

DAI OSB 40NG-035 Page 2 of 3 02-Dec-2014

# II PLANNING INFORMATION

# II.1 Material and Availability

See WI-OSB 40NG-035, latest effective issue.

### II.2 Special Tools

None.

### II.3 Labour Effort

Approx. 2 hours.

# II.4 Credit

None.

#### II.5 Reference Documents

DA 40 NG Airplane Maintenance Manual, Doc. No. 6.02.15, latest effective issue.

# III REMARKS

- All work must be done by a certified aircraft service station or a certified aircraft maintenance mechanic.
- 2. All work, in particular that which is not especially described in this Service Bulletin, must be done in accordance with the referenced Maintenance Manual.
- 3. Completion of all work must be recorded in the log book.
- 4. In case of doubt contact Diamond Aircraft Industries GmbH.



# Diamond Aircraft Industries GmbH N. A. Otto-Straße 5 2700 Wiener Neustadt Austria

DAI OSB 40NG-035 Page 3 of 3 02-Dec-2014

# EXECUTION REPORT TO SERVICE BULLETIN OSB 40NG-035

AIRPLANE INFORMATION			
Airplane Serial Number	_		_
Airplane Registration	_		_
Airplane Operator	_		_
Hours of operation of airplane	-		_
No. of landings	_		_
Hours of operation-engine	_		_
Typical operation of airplane	private,	club, training, other	
Date, Name, Sign			

Please fax the completed form to Fax No. +43-2622-26700-1369 or e-mail to airworthiness@diamond-air.at