Diamond Aircraft Industries GmbH N. A. Otto-Straße 5 2700 Wiener Neustadt Austria

DAI OSB 40NG-038 Page 1 of 3 26-May-2015

OPTIONAL SERVICE BULLETIN OSB 40NG-038

I <u>TECHNICAL DETAILS</u>

I.1 Category

Optional.

I.2 Airplanes affected

Type: DA 40 NG

Serial numbers: 40.N029, 40.N033, 40.N034, 40.N038 and subsequent

Airplanes converted to DA 40 NG via OSB D4-080 using

WI-OSB D4-080 Revision 4 or later.

I.3 Date of effectivity

07-May-2015

I.4 Time of Compliance

At owner's discretion

I.5 Subject

Improvement of powerplant cooling.

ATA-Code: 71-10

I.6 Reason

For operation under hot weather conditions DAI has approved optional provisions for improved cooling of the DA 40 NG. This Service Bulletin make these provisions available for airplanes already in service.

I.7 Concurrent Documents

None.

I.8 Approval

The technical information or instructions contained in this document relate to the Design Change Advisory No. OÄM 40-387, which has been approved under the authority of EASA Design Organization Approval ref. EASA.21J.052.

The technical content of this document has been approved under the authority of DOA ref. EASA.21J.052.

I.9 Accomplishments / Instructions

See WI-OSB 40 NG-038, latest effective issue.

Diamond Aircraft Industries GmbH N. A. Otto-Straße 5 2700 Wiener Neustadt Austria

DAI OSB 40NG-038 Page 2 of 3 26-May-2015

I.10 Mass (Weight) and CG

The change in mass and CG is negligible.

II PLANNING INFORMATION

II.1 Material and Availability

See WI-OSB 40 NG-038, latest effective issue.

II.2 Special Tools

None.

II.3 Labour Effort

Approx. 4 hours.

II.4 <u>Credit</u>

None.

II.5 Reference Documents

DA 40 NG Airplane Maintenance Manual, Doc. No. 6.02.15, latest effective issue.

III REMARKS

- All work must be done by a certified aircraft service station or a certified aircraft maintenance mechanic.
- 2. All work in particular that which is not especially described in this Service Bulletin, must be done in accordance with the referenced Maintenance Manual.
- 3. Completion of all work must be recorded in the log book.
- 4. In case of doubt contact Diamond Aircraft Industries GmbH.



Diamond Aircraft Industries GmbH N. A. Otto-Straße 5 2700 Wiener Neustadt Austria

DAI OSB 40NG-038 Page 3 of 3 26-May-2015

EXECUTION REPORT TO SERVICE BULLETIN OSB 40NG-038

AIRPLANE INFORMATION			
Airplane Serial Number			-
Airplane Registration			-
Airplane Operator			-
Hours of operation of airplane			-
No. of landings			-
Hours of operation-engine			-
Typical operation of airplane	private,	club, training, other _	
Date, Name, Sign			

Please fax the completed form to Fax No. +43-2622-26700-1369 or e-mail to airworthiness@diamond-air.at