

# OPTIONAL SERVICE BULLETIN

## NO. OSB-40-062

### **I TECHNICAL DETAILS**

#### **I.1 Category**

Optional

#### **I.2 Airplanes affected**

Type: DA 40

Serial Numbers: all

#### **I.3 Date of Effectivity**

01-Apr-2009

#### **I.4 Time of Compliance**

At owner's discretion

#### **I.5 Subject**

The installation of the Artex ME406 "ACE" ELT.

#### **I.6 Reason**

As of 01-February-2009 COSPAS-SARSAT no longer monitors the 121.5/243 MHz frequency.

### **I.7 Concurrent Documents**

Artex, Description, Operation, Installation and Maintenance Manual ME406, P/N 570-1600

### **I.8 Approval**

The technical information or instructions contained in this document relate to the Design Change Advisory No. OÄM 40-284, which has been approved under the authority of EASA Design Organization Approval No. EASA.21J.052.

The technical content of this document has been approved under the authority of DOA No. EASA.21J.052.

### **I.9 Accomplishment/Instructions**

Work Instruction NO. WI-OSB 40-062, latest effective issue.

### **I.10 Mass (Weight) and CG**

Negligible.

## **II PLANNING INFORMATION**

### **II.1 Material & Availability**

WI-OSB-40-062 is available through Diamond Aircraft.

### **II.2 Special Tools**

None.

### **II.3 Credit**

None.

### **II.4 Referenced Documents**

Work Instruction No. WI-OSB 40-062, latest effective issue.

### **III REMARKS**

- 1) All measures must be carried out by a certified aircraft maintenance station or a certified aircraft maintenance mechanic.
- 2) Accomplishment of the measures must be confirmed in the log book.
- 3) In case of any doubt, contact Diamond Aircraft Industries GmbH.



## EXECUTION REPORT TO SERVICE BULLETIN OSB 40-062

### AIRPLANE DATA

Airplane Serial Number: \_\_\_\_\_  
Airplane Registration: \_\_\_\_\_  
Airplane Operator: \_\_\_\_\_  
Hours of operation of airplane: \_\_\_\_\_  
No. of landings: \_\_\_\_\_  
Hours of operation-engine: \_\_\_\_\_  
Typical operation of airplane: private, club, training, other \_\_\_\_\_

---

Date, Name, Sign

Please fax the completed form to Fax No. +43-2622-26700-369 or e-mail to  
airworthiness@diamond-air.at