



Diamond Aircraft Industries G.m.b.H.
N.A. Otto-Straße 5
A-2700 Wiener Neustadt

DAI SI40-007
Page 1 of 1
18-Feb-2002
FT

SERVICE INFORMATION NO. SI40-007

I. TECHNICAL DETAILS

1.1 Airplanes affected:

DA 40 equipped with GARMIN GNS 430

1.2 Subject:

GARMIN GNS 430

ATA-Code: - - -

1.3 Reason:

Modification of the GARMIN GNS 430 unit due to the issuance of a **FAA AD 2001-23-17** that applies to certain GARMIN GNS 430 units installed on aircraft.

1.4 Information:

For detailed information see attached **FAA AD 2001-23-17**.

II. OTHERS

none