

TEMPORARY REVISION

TR-MÄM 40-1020

Removal of Pilot Gust Lock Mount

This Temporary Revision TR-MÄM 40-1020 is approved in conjunction with the Mandatory Design Change Advisory MÄM 40-1020 and is valid in conjunction with the latest revision of the DA 40 F Airplane Flight Manual until this temporary revision has been incorporated into the Airplane Flight Manual.

The limitations and information contained herein either supplement or, in the case of conflict, override those in the Airplane Flight Manual.

Doc. No.	Chapter	Affected Pages
6.01.02-E	8	8-7a

Instruction

- Print this document on yellow paper (single sided).
- Insert this cover page as the first page of the AFM.
- Insert the other pages of this Temporary Revision in front of the corresponding AFM pages.

Doc. # 6.01.02-E	TR-MÄM 40-1020	13-Sept-2018	Cover Page
------------------	----------------	--------------	------------

Affected Chapters:

8.4 GROUND HANDLING / ROAD TRANSPORT

8.4.3 PARKING

The Figures are amended to read:

