

---

**OPTIONAL SERVICE BULLETIN NO. OSB D4-113 REV. 0**

**I TECHNICAL DETAILS**

**I.1 Category**

Optional.

**I.2 Airplanes Affected**

Type: DA 40 D

S/N: D4.001 and subsequent.

**I.3 Date of Effectivity**

03 August 2023.

**I.4 Time of Compliance**

At owner's discretion.

**I.5 Subject**

Installation of Amerex 337TS fire extinguisher.

ATA code: 26-00

**I.6 Reason**

Due to the elimination of the substance Halon 1211 by the Canadian environmental legislation and discontinuation of the A620T fire extinguisher, Diamond Aircraft has approved the Amerex 337TS fire extinguisher as an alternate to the existing extinguisher. This Service Bulletin describes the installation of the Amerex 337TS fire extinguisher.

**I.7 Concurrent Documents**

None.

**I.8 Approval**

The technical information and instructions contained in this document relate to Design Change Advisories MÄM 40-1162 and MÄM DAIC-0042, which have been approved as part of the type design.

**I.9 Accomplishment/Instructions**

See WI-OSB D4-113, latest effective issue.

**I.10 Mass (Weight) and CG**

The change in mass and CG is negligible.

## **II PLANNING INFORMATION**

### **II.1 Material and Availability**

See WI-OSB D4-113, latest effective issue.

### **II.2 Special Tools**

None.

### **II.3 Labour Effort**

Approximately 1 hour will be required to accomplish this service bulletin.

This estimate is for direct labour performed by a technician, and it does not include setup, planning, familiarization, cure time, part fabrication, or tool acquisition.

### **II.4 Credit**

None.

### **II.5 Reference Documents**

DA 40 Series Airplane Maintenance Manual, Doc. No. 6.02.01, latest effective issue.

## **III REMARKS**

1. All work must be done by the appropriate authorized personnel.
2. All work, in particular which is not especially described in this service bulletin, must be done in accordance with the referenced maintenance manual.
3. Completion of all work must be recorded in the logbook.
4. In case of doubt, contact Diamond Aircraft Industries Inc.



---

**EXECUTION REPORT TO  
SERVICE BULLETIN  
OSB D4-113 REV. 0**

**AIRPLANE DATA**

Airplane serial number \_\_\_\_\_

Airplane registration \_\_\_\_\_

Airplane operator \_\_\_\_\_

Hours of operation of airplane (TSN) \_\_\_\_\_

Typical operation of airplane private, club, training, other: \_\_\_\_\_

**MAINTENANCE DATA**

Date of maintenance \_\_\_\_\_

Maintenance carried out by \_\_\_\_\_

During scheduled inspection?  Yes  No \_\_\_\_\_

---

Name \_\_\_\_\_ Signature \_\_\_\_\_ Date \_\_\_\_\_

Please e-mail the completed form to [Techpubs@diamondaircraft.com](mailto:Techpubs@diamondaircraft.com).