

SERVICE INFORMATION NO. SI D4-090

NOTE: SI's are used **only**:
1) To distribute information from DAI to our customers.
2) To distribute applicable information / documents from our suppliers to our customers with additional information.
Typically there is no revision service for SI's. Each new information or change of that will be sent along with a new SI.

I. TECHNICAL DETAILS

1.1 Airplanes affected:

All DA 40 D aircraft equipped with GARMIN G1000 Flight Deck Systems.

1.2 Subject:

GARMIN Service Alert No. 0801
ATA-Code: 34-00

1.3 Reason:

GARMIN has issued the Service Alert 0801 concerning the Supplemental Data Cards which should not be used to load Jeppesen NavData onto GARMIN GDU's.

1.4 Information:

For detailed technical information confer GARMIN – Service Alert No. 0801 which is applicable without any further additions or restrictions.

II. OTHERS

The GARMIN Service Alert No. 0801 is attached to this SI.

In case of doubt contact Diamond Aircraft Industries GmbH.



SERVICE ALERT

NO.: 0801

TO: All Garmin Aviation Service Centers
DATE: 25 January 2008
SUBJECT: Supplemental Data Cards Should Not Be Used To Load Jeppesen NavData

AFFECTED PRODUCTS

All G1000 Integrated Flight Deck systems.

DESCRIPTION

Some G1000 Pilot's Guides suggest that Jeppesen NavData can be loaded onto Garmin supplemental data cards. Due to issues encountered with loading Jeppesen NavData database information onto Garmin 010-00330-41 or 010-00330-42 supplemental data cards, Garmin no longer recommends this procedure.

NOTE

Loading Jeppesen Chartview data onto these supplemental data cards remains acceptable.

RESOLUTION

Load the Jeppesen NavData database information only onto blank SD cards for transferring data to GDU's.

Garmin is in the process of removing the statement that suggests loading NavData onto supplemental data cards from all G1000 Pilot's Guide documents.

NOTE

Garmin recommends the use of SanDisk SD cards to load Jeppesen data. If loading problems occur when using another brand of card, replace the card with a SanDisk card and reattempt the load.

© Copyright 2008
Garmin Ltd. or its subsidiaries
All Rights Reserved

Except as expressly provided herein, no part of this document may be reproduced, copied, transmitted, disseminated, downloaded or stored in any storage medium, for any purpose without the express prior written consent of Garmin. Garmin hereby grants permission to download a single copy of this document and of any revision to this document onto a hard drive or other electronic storage medium to be viewed and to print one copy of this document or of any revision hereto, provided that such electronic or printed copy of this document or revision must contain the complete text of this copyright notice and provided further that any unauthorized commercial distribution of this document or any revision hereto is strictly prohibited.