

# SUPPLEMENT N065 TO THE AIRPLANE FLIGHT MANUAL DA 42 NG

#### **OPERATION IN HONG KONG**

Doc. No. : 7.01.16-E

Date of Issue of the Supplement : 26-Nov-2012

Design Change Advisory : NÄM 42-065

This Supplement is approved by EASA on behalf of Hong Kong Civil Aviation Department under the authority of DOA No. EASA.21J.052 and EASA P/N 0010016520.

This airplane must be operated in compliance with the information and limitations contained herein.

Prior to operation the pilot must take notice of all information contained in this supplement to the Airplane Flight Manual.

DIAMOND AIRCRAFT INDUSTRIES GMBH N.A. OTTO-STR. 5 A-2700 WIENER NEUSTADT AUSTRIA



DA 42 NG AFM Supplement N065

Intentionally left blank.



## 0.1 RECORD OF REVISIONS

Rev. No.	Reason	Chap- ter	Page(s)	Date of Revision	Approval Note	Date of Approval	Date Inserted	Signature
1	Additional Information	0, 4A, 7	All except Cover Page	03-Dec-2012	Rev. 1 to AFM Supplement N065 to AFM Doc. No. 7.01.16-E is approved under the authority of DOA No. EASA 21J.052	04-Dec-2012		

Doc. # 7.01.16-E	Rev. 1	03-Dec-2012	Page 9-N065-3
2 3 3 1 1 1 3 1 1 1 5 2		00 200 20 .2	i age o mee



## **0.2 LIST OF EFFECTIVE PAGES**

	Chapter	Page	Date
ı		9-N065-1 9-N065-2	26-Nov-2012 03-Dec-2012
I	0	9-N065-3 9-N065-4	03-Dec-2012 03-Dec-2012
! !		9-N065-5 9-N065-6	03-Dec-2012 03-Dec-2012
ı	1	9-N065-7	03-Dec-2012
ı	2	9-N065-8	03-Dec-2012
ı	3	9-N065-9	03-Dec-2012
ı	4A	9-N065-9	03-Dec-2012
ı	4B	9-N065-10	03-Dec-2012
ı	5	9-N065-10	03-Dec-2012
ı	6	9-N065-10	03-Dec-2012
ı	7	9-N065-11	03-Dec-2012
ı	8	9-N065-12	03-Dec-2012



## **0.3 TABLE OF CONTENTS**

		Page
	1. GENERAL	9-N065-7
	2. OPERATING LIMITATIONS	9-N065-8
	3. EMERGENCY PROCEDURES	9-N065-9
	4A. NORMAL OPERATING PROCEDURES	9-N065-9
I	4B. ABNORMAL OPERATING PROCEDURES	-N065-10
ı	5. PERFORMANCE9	-N065-10
I	6. MASS AND BALANCE9	-N065-10
I	7. DESCRIPTION OF THE AIRPLANE AND ITS SYSTEMS 9.	-N065-11
I	8. AIRPLANE HANDLING, CARE AND MAINTENANCE 9-	N065 -12



DA 42 NG AFM Supplement N065

Intentionally left blank.

DA 42 NG AFM Supplement N065



Operation in Hong Kong

## 1. GENERAL

No change.



DA 42 NG AFM Supplement N065

#### 2. OPERATING LIMITATIONS

#### **2.15 LIMITATION PLACARDS**

Beside the Door Locking Device Installed in the Passenger's Door:

## **EMERGENCY EXIT:**

The keylock must be unlocked during flight!

緊急出口:飛行途中不可上鎖!



#### 3. EMERGENCY PROCEDURES

No change.

#### **4A. NORMAL OPERATING PROCEDURES**

#### **4A.6.11 APPROACH AND LANDING**

Approach:

Item 5 of the checklist is amended to read:

5. Landing and taxi lights . . . . . . . . . . . as required



DA 42 NG AFM Supplement N065

## **4B. ABNORMAL OPERATING PROCEDURES**

No change.

#### 5. PERFORMANCE

No change.

#### **6. MASS AND BALANCE**

No change.



#### 7. DESCRIPTION OF THE AIRPLANE AND ITS SYSTEMS

#### 7.10 ELECTRICAL SYSTEM

#### **7.10.1 GENERAL**

Landing and Taxi Lights

#### The following is added:

- For the purpose of flights in the Transport Category Passenger, Landing and Taxi light
- I shall be referred as Landing lights and operated simultaneously when used as Landing
- I light.



DA 42 NG AFM Supplement N065

## 8. AIRPLANE HANDLING, CARE AND MAINTENANCE

No change.