

TEMPORARY REVISION

TR-MÄM 42-1262

New Part Number for Electrical Fuel Pump

This Temporary Revision TR-MÄM-42-1262 is approved in conjunction with the Optional Design Change Advisory MÄM 42-1262 and is valid in conjunction with the latest revision of the DA 42 NG Airplane Flight Manual until this Temporary Revision has been incorporated into the Airplane Flight Manual.

The limitations and information contained herein either supplement or, in the case of conflict, override those in the Airplane Flight Manual or its previous Temporary Revisions.

The technical information contained in this document has been approved under the authority of DOA No. EASA.21J.052.

Doc. No.	Chapter	Affected Pages
7.01.16-E	6	6-30a

Instruction

- Print this document on yellow paper (single-sided).
- Insert this cover page as the first page of the AFM.
- Insert the other page of this TR in front of the corresponding AFM page.

Doc. # 7.01.16-E	TR-MÄM-42-1262	18-Jan-2023	Cover Page
------------------	----------------	-------------	------------



6.5 EQUIPMENT LIST AND EQUIPMENT INVENTORY

The following items are added to the Equipment List:

Airplane Serial No.:		Registration:		Date:		Mass		Lever Arm	
Description	Type	Part No.	Manufacturer	S/N	installed	lb	kg	in	m
LH fuel pumps (2x)		D64-9028-11-01	Bosch						
RH fuel pumps (2x)		D64-9028-11-01	Bosch						