TEMPORARY REVISION TR-MÄM-42-1265 New Fire Extinguisher

This Temporary Revision TR-MÄM-42-1265 is approved in conjunction with the Mandatory Design Change Advisory MÄM 42-1265 and is valid in conjunction with the latest revision of the DA 42 NG Airplane Flight Manual until this Temporary Revision has been incorporated into the Airplane Flight Manual.

The limitations and information contained herein either supplement or, in the case of conflict, override those in the Airplane Flight Manual or its previous Temporary Revisions.

The technical information contained in this document has been approved under the authority of DOA No. EASA.21J.052.

| Doc. No. | Chapter | Affected Pages |
|-----------|---------|----------------|
| 7.01.16-E | 3 | 3-58a |
| | 4 | 4A-7a |
| | 6 | 6-22a |

Instruction

- -Print this document on yellow paper (single-sided).
- -Insert this cover page as the first page of the AFM.
- -Insert the other pages of this TR in front of the corresponding AFM pages.

| Doc. # 7.01.16-E TR-MÄM-42-1 | 265 13-Mar-2023 | Cover Page |
|------------------------------|-----------------|------------|
|------------------------------|-----------------|------------|



3.11 SMOKE AND FIRE

The note is amended to read:

NOTE

| l I | The fire extinguisher is located on the cabin floor behind the co-pilot's seat. |
|----------------|--|
| | If AIR TOTAL HAL 1 is installed: To release the fire extinguisher out of the fire extinguisher mount, pull the fire extinguisher at the nozzle near the Y-spring. |
| | If Amerex A620T (OÄM 42-127) or Amerex 337TS (MÄM 42-1265) is installed: To release the fire extinguisher out of the fire extinguisher mount, open the holding strap and pull the fire extinguisher out. |

4A.6 CHECKLISTS FOR NORMAL OPERATING PROCEDURES

4A.6.1 PRE-FLIGHT INSPECTION

I. Cabin Check

Preparation:

The following item is amended to read:

| i | Fire extinguisher (if installed) | stowed and secured |
|---|----------------------------------|------------------------------|
| | | pressure in green arc |
| | if AIR TOTAL HAL 1 is installed | no damage of the tamper seal |



Temporary Revision New Fire Extinguisher

6.5 EQUIPMENT LIST AND EQUIPMENT INVENTORY

The following item is amended to read:

| Airplane Serial No.: | | Registration: | | Date: | | Mass | | Lever Arm | |
|----------------------|------|-----------------|-------------------|-------|-----------|------|----|-----------|---|
| Description | Туре | Part No. | Manufacturer | S/N | installed | lb | kg | in | m |
| Fire extinguisher | | AIR TOTAL HAL 1 | TOTAL Feuerschutz | | | | | | |

The follwing item is added to the Equipment list:

| Airplane Serial No.: | | Registration: | | Date: | | Mass | | Lever Arm | |
|----------------------|------|---------------|--------------|-------|-----------|------|----|-----------|---|
| Description | Туре | Part No. | Manufacturer | S/N | installed | lb | kg | in | m |
| Fire extinguisher | | 337TS | Amerex | | | | | | |

Doc. # 7.01.16-E TR-MÄM-42-1265 13-Mar-2023 Page 6-22a