

TEMPORARY REVISION
TR-OÄM 42-204/b & TR-OÄM 42-193/b
Additional Alternator & Recirculating Air -
Cabin Cooling

This Temporary Revision TR-OÄM 42-204/b & TR-OÄM 42-193/b is approved in conjunction with the Optional Design Change Advisories OÄM 42-204/v and OÄM 42-193/u and is valid in conjunction with the latest revision of the DA 42 NG Airplane Flight Manual until this Temporary Revision has been incorporated into the Airplane Flight Manual.

The limitations and information contained herein either supplement or, in the case of conflict, override those in the Airplane Flight Manual or its previous Temporary Revisions.

The technical information contained in this document has been approved under the authority of DOA No. EASA.21J.052.

Doc. No.	Chapter	Affected Pages
7.01.16-E	9	9-2a

Instruction

- Print this document on yellow paper (single-sided).
- Insert this cover page as the first page of the AFM.
- Insert the other pages of this TR in front of the corresponding AFM pages.

Doc. # 7.01.16-E	TR-OÄM 42-204/b & TR-OÄM 42-193/b	06-Oct-2023	Cover Page
------------------	--------------------------------------	-------------	------------

CHAPTER 9

SUPPLEMENTS

9.2 LIST OF SUPPLEMENTS

The following entry is added to the table:

<i>Airplane S/N:</i>		<i>Registration:</i>		<i>Date:</i>	
Sup. No.	Title	Rev. No.	Date	applicable	
				YES	NO
S07	Recirculating Cabin - Air Cooling	1	01-Apr-2014	<input type="checkbox"/>	<input type="checkbox"/>

Doc. # 7.01.16-E	TR-OÄM 42-204/b & TR-OÄM 42-193/b	06-Oct-2023	9-2a
------------------	--------------------------------------	-------------	------