

TEMPORARY REVISION AMM-TR-MÄM-42-1235 Placard Overview Correction

This Temporary Revision AMM-TR-MÄM-42-1235 is approved in conjunction with the Mandatory Design Change Advisory MÄM 42-1235 and is valid in conjunction with the Airplane Maintenance Manual (AMM) until this Temporary Revision has been incorporated into the AMM.

The limitations and information contained herein either supplement or, in the case of conflict, override those in the AMM.

The technical information contained in this document has been approved under the authority of DOA No. EASA.21J.052.

Doc. No.	Section	Affected Pages
7.02.15	11-20-00	1a, 1aa

Instruction

- Print this document on yellow paper (double-sided).
- $-% \frac{1}{2}\left(-\right) =-\left(-\right) \left(-\right) =-\left(-\right) \left(-\right)$
- Insert the other pages of this Temporary Revision adjacent to or in front of the corresponding AMM pages.



Intentionally left blank



CHAPTER 11 PLACARDS AND MARKINGS Section 11-20

Exterior Placards and Markings

1. General

Figure 1 is amended to read:




Figure 1: Exterior Placards



Intentionally left blank