

# OPTIONAL SERVICE BULLETIN

## OSB 42-121

## OSB 42NG-058

### **I TECHNICAL DETAILS**

#### **I.1 Category**

Optional.

#### **I.2 Airplanes affected**

Type: DA 42, DA 42 M DA 42 NG, DA 42 M-NG  
Serial numbers: 42.004 and subsequent  
42.AC001 and subsequent  
42.M001 and subsequent  
42.N001 and subsequent  
42.NC001 and subsequent  
42.MN001 and subsequent

#### **I.3 Date of effectivity**

22-Jun-2016

#### **I.4 Time of Compliance**

At owner's discretion

#### **I.5 Subject**

Installation of LED Position Lights and ACL.

ATA-Code: 33-40

#### **I.6 Reason**

LED Position Lights and ACL have been approved for installation. This Service Bulletin describes the retrofit installation on airplanes already in service.

#### **I.7 Concurrent Documents**

None.

#### **I.8 Approval**

The technical information or instructions contained in this document relate to the Design Change Advisory No. OÄM 42-222, which has been approved under the authority of EASA Design Organization Approval ref. EASA.21J.052.

The technical content of this document has been approved under the authority of DOA ref. EASA.21J.052.

**I.9 Accomplishments / Instructions**

See WI-OSB 42-121/WI-OSB 42NG-058, latest effective issue.

**I.10 Mass (Weight) and CG**

Approx. 1.5 kg (3.4 lbs) weight reduction.

**II PLANNING INFORMATION****II.1 Material and Availability**

See WI-OSB 42-121/WI-OSB 42NG-058, latest effective issue.

**II.2 Special Tools**

None.

**II.3 Labour Effort**

Approx. 2 hours.

**II.4 Credit**

None.

**II.5 Reference Documents**

DA 42 Series Airplane Maintenance Manual, Doc. No. 7.02.01, latest effective issue.

DA 42 NG Airplane Maintenance Manual, Doc. No. 7.02.15, latest effective issue.

**III REMARKS**

1. All work must be done by a certified aircraft service station or a certified aircraft maintenance mechanic.
2. All work, in particular that which is not especially described in this Service Bulletin, must be done in accordance with the referenced Maintenance Manual.
3. Completion of all work must be recorded in the log book.
4. In case of doubt contact Diamond Aircraft Industries GmbH.

**EXECUTION REPORT TO  
SERVICE BULLETIN  
OSB 42-121  
OSB 42NG-058**

AIRPLANE INFORMATION

Airplane Serial Number \_\_\_\_\_

Airplane Registration \_\_\_\_\_

Airplane Operator \_\_\_\_\_

Hours of operation of airplane \_\_\_\_\_

No. of landings \_\_\_\_\_

Hours of operation-engine     LH     \_\_\_\_\_

   RH     \_\_\_\_\_

Typical operation of airplane     private, club, training, other \_\_\_\_\_

\_\_\_\_\_  
Date, Name, Sign

Please fax the completed form to Fax No. +43-2622-26700-1369 or e-mail to  
[airworthiness@diamond-air.at](mailto:airworthiness@diamond-air.at)