

SERVICE INFORMATION

No. SI 42NG-072

NOTE: SI's are used only:
1) To distribute information from DAI to our customers.
2) To distribute applicable information/documents from our suppliers to our customers with additional information.
Typically there is no revision service for SI's. Each new information or change of that will be sent along with a new SI.

I. TECHNICAL DETAILS

1.1 Airplanes affected:

DA 42 NG /M-NG airplanes with Garmin G1000 System Software Version P/N 010-00670-12

1.2 Subject:

GARMIN Service Alert No. 1456 Rev. A

ATA-Code: 34-00

1.3 Reason:

GARMIN has issued Service Alert No. 1456 Rev. A, describing that under certain conditions the published VNAV altitude constraint for the remaining final approach fix (FAF) waypoint is changed to a VNAV altitude constraint of zero foot.

1.4 Information:

For detailed technical information refer to GARMIN Service Alert No. 1456 Rev. A which is applicable without any further additions or restrictions.

II. OTHERS

GARMIN Service Alert No. 1456 Rev. A is attached to this Service Information.

In case of doubt contact GARMIN Ltd.