

TEMPORARY REVISION

AMM-TR-MÄM 42-1300

Supplier Contact Update

This Temporary Revision AMM-TR-MÄM 42-1300 is approved in conjunction with the Mandatory Design Change Advisory MÄM 42-1300 and is valid in conjunction with the Airplane Maintenance Manual (AMM) until this Temporary Revision has been incorporated into the AMM, latest revision.

The limitations and information contained herein either supplement or, in the case of conflict, override those in the AMM.

The technical information contained in this document has been approved under the authority of DOA No. EASA.21J.052.

Doc. No.	Section	Affected Pages
7.02.01	51-30-00	1a, 1aa

Instruction

- Print this document double-sided on yellow paper (odd pages and "a" pages on front sides, even pages and "aa" pages on reverse sides).
- Insert this cover page as the first page of the AMM.
- Insert the other pages of this Temporary Revision in front of the corresponding AMM pages.

Intentionally left blank

AFFECTED CHAPTER:

CHAPTER 51
STANDARD PRACTICES/STRUCTURES
Section 51-30-00
Materials

2. Approved Materials**A. Resin System**

The following paragraph is amended to read:

Resin : L285
Hardener : H286
Mixture : 100 parts resin and 40 ±2 parts of hardener (by weight)

Supplier : Westlake Esslingen GmbH
Fritz-Müller-Straße 114
D-73730 Esslingen am Neckar, Germany
Phone: +49-711-389800-0

Intentionally left blank