
TEMPORARY REVISION

TR-OÄM-62-1002

28V Power Outlet Option

This Temporary Revision TR-OÄM-62-1002 is approved in conjunction with the Optional Design Change Advisory OÄM 62-1002 and is valid in conjunction with the latest revision of the DA 62 Airplane Flight Manual until this Temporary Revision has been incorporated into the Airplane Flight Manual.

The limitations and information contained herein either supplement or, in the case of conflict, override those in the Airplane Flight Manual or its previous Temporary Revisions.

The technical information contained in this document has been approved.

Doc. No.	Chapter	Affected Pages
7.01.25-E	7	7-68a

Instruction

- Print this document on yellow paper (single-sided).
- Insert this cover page as the first page of the AFM.
- Insert the other page of this TR in front of the corresponding AFM page.

Doc. # 7.01.25-E	TR-OÄM-62-1002	06-Apr-2018	Cover Page
------------------	----------------	-------------	------------

7.10 ELECTRICAL SYSTEM

7.10.1 GENERAL

The Paragraph is added:

28V Power Outlet Option (if OÄM 62-1002 is installed)

The DA 62 has a 28V power outlet at the lower right of the Instrument Panel. Only equipment, that has been certified specifically for this outlet may be used. In case of any malfunction of the equipment or any of the alternators, the equipment must be disconnected or switched off.

For more information refer to the Airplane Maintenance Manual.