

LIST OF APPLICABLE PUBLICATIONS

MODEL DA 62

Revision 80 Updates

Doc. No.	Description	Rev	Status
AMM-TR-25-03	Fuel Filler Cap Overhaul	-	2025-05-07
SI62-044	Fuel Contamination	-	2025-05-07

Full Listing Doc. No.	Description	Rev	Status
7.05.25 Chapter 1	List of Applicable Publications (LOAP) - This document	80	2025-05-07
Aircraft Manuals			
11.01.05	Airplane Flight Manual	1	2019-10-24
Supplement A33	SBAS and P-RNAV Operation with Garmin Integrated Avionic System G1000 and G1000 NXi	-	2019-08-15
Supplement A34	Electronic Stability and Protection	-	2019-01-31
Supplement A35	Garmin GTX 335R/345R with ADS-B	-	2020-03-20
Supplement M15	On Top Exhaust System	-	2019-01-31
Supplement N022	Operation in China	-	2018-11-23
Supplement N023	Operation in Brazil	-	2020-07-20
Supplement N024	Operation in India	-	2020-07-13
Supplement N025	Operation in Mexico	-	2019-01-31
Supplement O04	Operation without Unfeathering Accumulator	-	2019-01-31
Supplement O08	Pilot's Removable Stick	-	2019-01-31
Supplement O09	Operation with D64-9028-11-01 Fuel Pumps	1	2024-01-16
Supplement S02	Ice Protection System	-	2019-01-31
Supplement S03	Ice Protection System for Flight into Known Icing	-	2019-01-31
Supplement S04	Continuous Flow Oxygen System	-	2019-01-31
Supplement S06	G1000 Synthetic Vision Technology	-	2019-01-31
Supplement S07	Recirculating Air Cabin Cooling	-	2019-01-31
TR-MÄM 62-1007	Garmin G1000 NXi Phase II	-	2019-10-19
TR-MÄM 62-1035	Parking Brake Procedure & Comant CI 105-16 Antenna	-	2019-11-06

7.05.25 Chapter 1 R80

Page 1 of 7
07 May 2025

LIST OF APPLICABLE PUBLICATIONS

MODEL DA 62

Full Listing			
Doc. No.	Description	Rev	Status
TR-MÄM 62-1056	AHY Engine	-	2020-02-27
TR-MÄM 62-1062	Kathon FP 1.5 Biocide Discontinuation	-	2020-05-27
TR-MÄM 62-1063	Use of Alt. Static Source	-	2020-12-21
TR-MÄM 62-1066	BHY Engine	-	2020-08-24
TR-MÄM 62-1083	D64-9028-11-01 Fuel Pumps	-	2023-03-01
TR-MÄM DAIC-0042	Amerex 337TS Fire Extinguisher	-	2023-04-01
TR-OÄM 62-1019	Avidyne TAS6XXA	-	2021-03-01
TR-OÄM 62-1016	Garmin GWX 75 Weather Radar	-	2023-06-21
TR-MÄM-62-1135	Fuel System Limitations	-	2024-04-29
TR-MÄM-62-1118	Replacement of Flap Actuator Motor	-	2025-02-26
7.01.25	Airplane Flight Manual	4	2017-11-14
Supplement A33	Integrated Avionics System Garmin G1000 and G1000 NXi, SBAS and P-RNAV Operation	1	2017-01-31
Supplement A34	Electronic Stability and Protection (ESP)	-	2015-04-01
Supplement M15	On Top Exhaust System	-	2017-08-18
Supplement N023	Operation in Brazil	-	2017-03-15
Supplement N024	Operation in India	-	2016-09-15
Supplement N025	Operation in Mexico	-	2016-06-16
Supplement O04	Operation without Unfeathering Accumulator	-	2015-11-14
Supplement O08	Pilot's Removable Stick	-	2016-01-30
Supplement S02	Ice Protection System	1	2015-11-15
Supplement S03	Ice Protection System for Flight Into Known Icing	2	2017-05-05
Supplement S04	Continuous Flow Oxygen System	1	2015-11-14
Supplement S06	G1000 Synthetic Vision Technology	1	2016-09-20
Supplement S07	Recirculating Air - Cabin Cooling	1	2016-09-08
TR-OÄM 62-038	On Top Exhaust System	-	2017-08-18
TR-17-05	Change in Type Design Responsibility	-	2017-11-15

7.05.25 Chapter 1 R80

LIST OF APPLICABLE PUBLICATIONS

MODEL DA 62

Full Listing Doc. No.	Description	Rev	Status
TR-OÄM 62-1002	28V Power Outlet Option	-	2018-07-06
7.02.25	Airplane Maintenance Manual (English)	3	2021-04-08
7.02.25-M15	Installation Instructions for System M15 - On Top Exhaust System	-	2017-08-18
7.02.25-N022	Operation in China	-	2018-11-23
7.02.25-N023	Operation in Brazil	-	2017-03-15
7.02.25-N025	Operation in Mexico	-	2016-06-16
AMM-TR-OAM-62-005	Amendment to the R&I of the RACC Central Unit (if OÄM 62-005 is installed)	0	2024-01-23
AMM-TR-MÄM 62-1083	Use of Fuel Additives	-	2023-04-01
AMM-TR-MÄM 62-1106	Wording change to Chapter 04 MSI	-	2023-01-11
AMM-TR-MÄM 62-1130	Introduction of Additional Inspection of Center Wing Spar B.	-	2023-09-27
AMM-TR-25-01	Copper Tape/ EMI Shielding Inspection/ Repair	-	2025-01-23
AMM-TR-25-05	Coolant Level Sensor Operational Test	-	2025-02-13
AMM-TR-MÄM-62-1118	Flap Actuator Motor	-	2025-02-26
AMM-TR-25-03	Fuel Filler Cap Overhaul	-	2025-05-07
7.03.25	Illustrated Parts Catalogue (IPC)	(N/A)	Available Online
11.11.01	Master Minimum Equipment List (MMEL)	1	2017-01-31
Service Bulletins			
MSB 62-002	Software for E4P-C engine, approved versions	7	2023-09-21
MSB 62-003	Software for Garmin G1000; approved software systems, manifests and configurations	9	2024-04-01
OSB 62-004	Switch between Passenger Seat Row 2 (7-Seat-Configuration) and Rear Baggage Compartment (5-Seat-Configuration) and vice versa	2	2022-12-06
OSB 62-005	Installation of additional "Lemo" headset jacks	-	2016-04-04
OSB 62-006	Retrofit Installation of Sun Visors	-	2016-06-17

7.05.25 Chapter 1 R80

LIST OF APPLICABLE PUBLICATIONS

MODEL DA 62

Full Listing Doc. No.	Description	Rev	Status
OSB 62-007	Retrofit Installation of Tablet Mount on A-Column	-	2017-01-31
OSB 62-008	Installation of wiring provisions for Heated Static Ports and Aux Fuel Quantity Indication	-	2016-10-18
OSB 62-009	Approval for Flight Into Known Icing Conditions	1	2016-11-08
RSB 62-010	Replacement of the turbocharger V-clamps	1	2017-11-02
OSB 62-012	Installation of power plant cooling improvement	1	2016-12-12
RSB 62-013	Improved mounting of 2nd Alternator	-	2017-03-08
OSB 62-014	Installation of larger fuel cooler and improved NACA duct	1	2018-08-16
OSB 62-015	Installation of armrest with integrated keypad	-	2017-05-24
OSB 62-016	Implementation of the increased Maximum Zero Fuel Mass of 2200 kg	1	2017-06-06
RSB 62-018	Inspection of rear Rudder Cable Pulley	-	2017-11-13
RSB 62-019	Replacement of TKS Propeller Nozzle	-	2017-11-13
MSB 62-020	Inspection of the middle and rear passenger seat lap safety belt connections	-	2018-02-09
MSB 62-024	Fuel Tank Interconnect Hose (Flexible Coupling) Replacement	2	2019-08-29
OSB 62-025	Installation Garmin NXI Phase II Equipment	1	2020-06-22
MSB 62-026	Inspection of Bonding Cables in Engine Installation	-	2019-09-20
MSB 62-027	Modification to the installation of heated static ports	1	2019-12-05
MSB 62-028	Baggage Net Latches	1	2021-07-06
MSB 62-029	Drilling of drain holes in the fuselage	-	2021-02-25
MSB 62-030	Cowling Lightning Protection	1	2020-07-01
MSB 62-031	Replacement of the autopilot bridle cable clamps	-	2020-02-25
OSB 62-032	Installation of unfeathering accumulators	-	2020-01-13
OSB 62-033	Installation of Garmin GTX 345R Transponder (ADS-B)	1	2020-09-03
OSB 62-034	Installation of Garmin Flight Stream (FS510)	-	2020-03-20
MSB 62-035	Bonding cables in engine nacelles	-	2020-07-27
MSB 62-036	Use of AFM Doc. No. 11.01.05-E	2	2020-08-24
MSB 62-037	Transfer to Type Certificate A00012NY	2	2021-12-23
MSB 62-038	Inspection of fuel filter installation	-	2021-09-30
OSB 62-039	Installation of an updated ELT bracket	-	2022-11-24

LIST OF APPLICABLE PUBLICATIONS

MODEL DA 62

Full Listing Doc. No.	Description	Rev	Status
OSB 62-040	Installation of fuel probes with sealed connectors	-	2023-03-30
MSB 62-042	Rudder rib correction	1	2023-10-19
OSB 62-043	Removal of unfeathering accumulators	-	2023-09-21
OSB 62-044	Replacement of CI 2580-220 antenna with C1 2728-410 antenna	1	2023-09-28
MSB 62-045	Inspection of starter wiring connection	2	2023-09-28
OSB 62-046	Installation of Amerex 337TS fire extinguisher	-	2023-08-03
OSB 62-047	Installation of Garmin GWX 75 weather radar	1	2023-10-12
OSB 62-048	Installation of alternate electric fuel pumps	-	2023-07-11
MSB 62-049	Installation of hinged drain cover	3	2024-11-21
RSB 62-050	Installation of Bowden cable extension for parking brake	-	2023-09-21
MSB 62-051	Replacement of the Main Landing Gear and Nose Landing Gear retaining rings.	1	2024-03-24
MSB 62-052	Horizontal stabilizer connecting bolt torque inspection	-	2023-09-18
MSB 62-055	Unblocking of drain holes underneath the center wing.	-	2024-06-26
Service Information Letters			
SI62-002	Garmin Service Alert No. 1605 Rev. A, probable AFCS armed mode cancellation in certain navigation modes	-	2016-02-19
SI62-003	Austro Engine MSB-E4-020, Inspection of Gearbox Housing	-	2016-03-04
SI62-004	Garmin Service Advisory No. 1612 Revision A, Update of the IGRF (International Geomagnetic Reference Field) Magnetic Field Model from base year 2010 to 2015	-	2016-09-14
SI62-005	EASA-AD: Amendment of the applicable AFM, and for engines operated under certain circumstances, the replacement of the engine timing chain	-	2017-06-19
SI62-006	Austro Engine MSB-E4-022/1, Replacement of certain batches of the Waste Gate Controller at E4 engines and the installation of a spring loaded circlip on all E4 engines	-	2017-11-13
SI62-007	Austro Engine MSB-E4-024/1, Replacement of the standard circlip at the Waste Gate Controller at E4 engines with a spring loaded circlip	-	2017-11-13
SIDA62-001	Change in Type Design Responsibility	-	2017-11-15
SI62-008	FAA-AD 2018-07-16 and EASA-AD 2017-0250: Lifetime limit to waste gate controller and replacement of waste gate rod circlips to prevent unsafe condition due to disconnection	-	2018-04-04

LIST OF APPLICABLE PUBLICATIONS

MODEL DA 62

Full Listing Doc. No.	Description	Rev	Status
SI62-009	EASA-AD 2018-0125: ATA 72 - Engine - Turbocharger Waste Gate Controller and Control Rod Circlip - Life Limit/Modification	-	2018-06-14
SI62-010	Air Intake System Hose	3	2018-10-18
SI62-011	Service Information Letter for 164-25700 Brake Disc	-	2018-09-19
SI62-012	Service Information Letter for Production Residue in Air filter	-	2018-09-20
SI62-013	Austro Engine MSB-E4-025 Fuel Injectors DA62	-	2018-10-22
SI62-014	FAA AD 2018-18-02: Austro Engine GmbH Engine Timing Chain	-	2018-11-28
SI62-015	EASA AD 2019-0041: Life limit to Austro Engine timing chain and fuel injectors	-	2019-03-08
SI62-016	New AFM for the DA 62	-	2019-04-12
SI62-017	Governor Adjustment of MIN/MAX Stop Settings	-	2019-06-20
SI62-018	Fuel hose P/N correction	-	2019-09-20
SI62-019	Fire Resistant Cowlings	-	2019-10-03
SI62-022	DUPONT product discontinuation letter	-	2020-05-20
SI62-023	Aircraft cleaning and disinfection recommendations	-	2020-05-21
SI62-024	Installation of vented access panels	-	2020-08-11
SI62-025	Inspection of safety ropes in the engine installation	-	2021-02-01
SI62-026	FAA AD 2020-22-14: Replacement of the wastegate controller and control rod circlip	-	2021-01-01
SI62-027	EASA AD 2021-0055-E and Austro Engine MSB-E4-030 - Oil Pump Replacement	-	2021-02-25
SI62-028	EASA AD 2021-0550-E and Austro Engine MSB-E4-030 Rev. 3 - Oil Pump Replacement - with updated serial number effectivity	-	2021-03-18
SI62-029	EASA AD 2021-0143-E and Austro Engine MSB-E4-031 - Oil Pump Replacement	-	2021-06-16
SI62-030	Austro Engine MSB-E4-034/2, MSB-E4-035, and EASA AD 2021-0203-E	-	2021-09-23
SI62-031	HPP Gear Modification	-	2021-09-30
SI62-032	Austro Engine MSB-E4-036 and EASA AD 2021-0274-E	-	2021-12-16
SI62-033	Austro Engine MSB-E4-039 - Oil analysis and piston replacement	-	2022-11-17
SI62-034	Inspection of ECU backup battery wiring	-	2022-11-17
SI62-036	Garmin Service Advisory No. 22106 Rev. A - G1000 NXi Systems Database Update	-	2022-12-06
SI62-039	Service Information Letter to introduce Austro Engine MSB-E4-042_r0	-	2024-02-07
SI62-042	EASA AD-2024-0172-E Piston Borescope Inspection	-	2024-08-29

Diamond Aircraft Industries

LIST OF APPLICABLE PUBLICATIONS

MODEL DA 62



Full Listing Doc. No.	Description	Rev	Status
SI62-043	Improved Routing of Cabin Heat Bowden Cable	-	2024-11-21
SI62-044	Fuel Contamination	-	2025-05-07