

Diamond Aircraft Industries GmbH N. A. Otto-Straße 5 2700 Wiener Neustadt, Austria DAI OSB 62-009/1 Page 1 of 3 8-Nov-2016

OPTIONAL SERVICE BULLETIN OSB 62-009/1 SUPERSEDES OSB 62-009

I TECHNICAL DETAILS

I.1 Category

Optional.

I.2 Airplanes affected

 Type:
 DA 62

 Serial numbers:
 62.007, 62.009 through 62.034

I.3 Date of effectivity

18-Oct-2016

I.4 <u>Time of Compliance</u>

At owner's discretion

I.5 Subject

Approval for Flight Into Known Icing Conditions.

ATA-Code: 34-00

I.6 <u>Reason</u>

For Flight Into Known Icing approval, electrically heated static ports must be installed, the limitation placard must be exchanged and the AFM must be updated. This Service Bulletin describes the actions necessary for airplanes already in service.

I.7 Concurrent Documents

None.

I.8 Approval

The technical information or instructions contained in this document relate to the Design Change Advisory No. OÄM 62-003, which has been approved under the authority of EASA Design Organization Approval ref. EASA.21J.052.

The technical content of this document has been approved under the authority of DOA ref. EASA.21J.052.

I.9 Accomplishments / Instructions

See WI-OSB 62-009, latest effective issue.

I.10 Mass (Weight) and CG

See WI-OSB 62-009, latest effective issue.



II PLANNING INFORMATION

II.1 Material and Availability

See WI-OSB 62-009, latest effective issue.

II.2 Special Tools

None.

II.3 Labour Effort

Approx. 30 hours.

II.4 Credit

None.

II.5 <u>Reference Documents</u>

DA 62 Airplane Maintenance Manual, Doc. No. 7.02.25, latest effective issue.

III <u>REMARKS</u>

- 1. All work must be done by a certified aircraft service station or a certified aircraft maintenance mechanic.
- 2. This Service Bulletin may ONLY be done by Diamond Aircraft Industries.
- 3. All work, particular that which is not especially described in this Service Bulletin, must be done in accordance with the referenced Maintenance Manual.
- 4. Completion of all work must be recorded in the log book.
- 5. In case of doubt contact Diamond Aircraft Industries GmbH.



Diamond Aircraft Industries GmbH N. A. Otto-Straße 5 2700 Wiener Neustadt, Austria DAI OSB 62-009/1 Page 3 of 3 8-Nov-2016

EXECUTION REPORT TO SERVICE BULLETIN OSB 62-009/1

AIRPLANE INFORMATION			
Airplane Serial Number			-
Airplane Registration			-
Airplane Operator			-
Hours of operation of airplane			-
No. of landings			-
Hours of operation-engine	LH		-
	RH		-
Typical operation of airplane	private,	club, training, other	

Date, Name, Sign

Please fax the completed form to Fax No. +43-2622-26700-1369 or e-mail to airworthiness@diamond-air.at