Diamond Aircraft Industries

OPTIONAL SERVICE BULLETIN





OPTIONAL SERVICE BULLETIN NO. OSB 62-046 REV. 0

I TECHNICAL DETAILS

I.1 Category

Optional.

I.2 Airplanes Affected

Type: DA 62

Serial Numbers: 62.264 and prior

62.C071 and prior

I.3 Date of Effectivity

03 August 2023.

I.4 Time of Compliance

At owner's discretion.

I.5 Subject

Installation of Amerex 337TS fire extinguisher.

ATA code: 26-00.

I.6 Reason

Due to the elimination of the substance Halon 1211 by the Canadian environmental legislation, Diamond Aircraft has approved the Amerex 337TS fire extinguisher as an alternate to the existing extinguishers, as it utilizes Halotron BrX (2-BTP) as the extinguishing agent. This Service Bulletin describes the installation of the Amerex 337TS Fire Extinguisher.

I.7 Concurrent Documents

None.

I.8 Approval

The technical information and instructions contained in this document relate to Design Change Advisories MÄM 62-1107 and MÄM DAIC-0042, which have been approved as part of the type design.

I.9 Accomplishment/Instructions

See WI-OSB 62-046, latest effective issue.

Diamond Aircraft Industries

OPTIONAL SERVICE BULLETIN



Model DA 62

I.10 Mass (Weight) and CG

The change in mass and CG is negligible.

II PLANNING INFORMATION

II.1 Material and Availability

See WI-OSB 62-046, latest effective issue.

II.2 Special Tools

None.

II.3 Labour Effort

Approximately 1 hour will be required to accomplish this service bulletin.

This estimate is for direct labour performed by a technician, and it does not include setup, planning, familiarization, cure time, part fabrication, or tool acquisition.

II.4 Credit

None.

II.5 Reference Documents

DA 62 Airplane Maintenance Manual, Doc. No. 7.02.25, latest effective issue.

III REMARKS

- 1. All work must be completed by the appropriate authorized personnel.
- 2. All work, in particular which is not especially described in this service bulletin, must be done in accordance with the referenced maintenance manual.
- 3. Completion of all work must be recorded in the logbook.
- 4. In case of doubt, contact Diamond Aircraft Industries.

Page 2 of 3 03 August 2023

Diamond Aircraft Industries

OPTIONAL SERVICE BULLETIN





SERVICE BULLETIN OSB 62-046 REV. 0

AIRPLANE DATA Airplane serial number Airplane registration Airplane operator Hours of operation of airplane (TSN) Typical operation of airplane private, club, training, other: **MAINTENANCE DATA** Date of maintenance Maintenance carried out by During scheduled inspection? Yes ☐ No Name Signature Date

Please e-mail the completed form to Techpubs@diamondaircraft.com.