

HOFFMANN AIRCRAFT Ges.m.b.H.

Richard Neutra-Gasse 5
A-1210 W i e n

S E R V I C E B U L L E T I N N o . 2 3

Affected Aircraft: DIMONA H-36

Subject: Modification to the original austrian version

Reason: Type approval for Italy

Required actions: 1. The marking of the RPM-indicator shall correspond to the RPM limitation in accordance to item 2.4, page 9 of Flight Manual, italian edition, dated May, 25 th 1988

 2. The marking of the fuel quantity indicator shall indicate 0, 1/4, 1/2, 3/4, 1 of the full capacity in the fuel tank (the marking shall be on the instrument and not on the glass).

 3. The placards will be in accordance with item 2.14, page 15, 16 and 17 of the Flight Manual, italian edition, dated May 25th 1988.

 4. The ventilation/heating duct between fire wall and flap valve shall be made of fire proof material.

 5. The provision for protection against fuel leakage on manifold joints near carburetor and better segregation of DC regulator, electrical system and fuel system shall be provided. See attached drawings.


 6. Pitot static system shall be provided with strainer.

Urgency: Before registration in Italy

Weight and balance: Not affected

Note: On new aircraft the actions will be done and certified by the manufacturer. On used aircraft the actions must be done by a certified repair and maintenance shop and attested in the log book.

Vienna, May 25th 1988 -


Dipl.-Ing. L. Osvaldik

approved by RAI: 1 GIU. 1988





* Bauteil Wandstärke 0,3 mm

REF: SB.23

FAX: RAI; 06 67 81 318

140

55




Druck 11
Leakage Protection
Vot

REVERSE ACCOUNT
XXXXXXXXXXXXXXXXXXXX
XXXXXXXXXXXXXXXXXXXX
XXXXXXXXXXXXXXXXXXXX

117 36
GTR

Werkstoff: Aluminium




Werkstoff: Aluminium
 Profil: Aluminium 6061-T6

NOVEMBER 1988
 WERNER KLOPPSCHMIDT
 Maschinenbau
 A 12111 Wien, Rudolph-Wilhelms-Strasse 5
 Tel. 43 1 478 1800-4, 478 1800-5

Werner Kopp

H36



Handwritten text:
488 172
Hoffmann
Technische Zeichnung
Mittelpunkt
Einzel
zeichnung

HOFFMANN ARBCRAFT
P.L. 5-1/2
A. 1218 Wert. Nr. 1218
A. 1218 Wert. Nr. 1218

Handwritten text:
41/39
A. 1218

I T A L I A N
=====

F L I G H T
=====

M A N U A L
=====

HOFFMANN AIRCRAFT
FLUGZEUGPRODUKTION und ENTWICKLUNG
Gesellschaft m. b. H.
A-1014 Wien, Richard-Strauss-Gasse 5
Tel. 122 100

25. Mai 1983

HOFFMANN AIRCRAFT

HOFFMANN AIRCRAFT CORP

P. O. Box No. 100

A-1214 Vienna

Austria

Phone (0.22 2/39 88 18 or 39 89 05

FLIGHT MANUAL

H36 DIMONA

This Flight Manual must be carried on board of the motorglider at all times.

Reg.No.: Ser.No.:

Owner :

.....

.....

Austrian edition of operating instructions is approved under § 33 ZLLW, Bundesgesetzblatt 415, Aug. 17 1983

Published 23. Mai 1982

BAZ-approved

7. JUNI 1988



Approval of translation has been done by best knowledge and judgement. In any case the original text in German language is authoritative.

Section 0

Hoffmann Flugzeugbau

Revisions

H 36 Dimona

PILOTS OPERATING HANDBOOK

LOG OF REVISIONS

Revision Number and Date	Revised Pages	Description of Revision

All manuals for the Hoffmann H 36 can be ordered from:
 Hoffmann Aircraft, Richard - Neutra - Gasse 5, P.O.Box 100,
 A - 1214 Vienna / Austria

7. JUNI 1988



WARNING!

This handbook should not be used for operational purpose unless it is maintained in a current status.

25. MAI 1988