TEMPORARY REVISION TR-MÄM-36-300 RELEASE 100

This Temporary Revision TR-MÄM-36-300 is approved in conjunction with the Mandatory Design Change Advisory MÄM 36-300 and is valid in conjunction with the latest revision of the HK 36 TC-100-Airplane Flight Manual until this temporary revision has been incorporated into the Airplane Flight Manual.

The limitations and information contained herein either supplement or, in the case of conflict, override those in the Airplane Flight Manual.

The technical information contained in this document has been approved under the authority of DOA No. EASA.21J.052.

Doc. No.	Section	Affected Pages	
3.01.12-E	7	7 - 5a 7 - 11a	

Instruction

-) Print this document on yellow paper (single-sided).
-) Insert this cover page as the first page of the AFM.
-) Insert the other pages of this Temporary Revision in front of the corresponding AFM pages.

Doc. No. 3.01.12-E	TR-MÄM-36-300	05-May-2006	Cover Page
--------------------	---------------	-------------	------------



Temporary Revision Release 100

7.5 LANDING GEAR SYSTEM

Parking Brake

The first sentence of the first paragraph is amended to read:

The draw-button is located on the center console behind the trim lever or on the center console below the instrument panel.

HK 36 TC-100 AFM



Temporary Revision Release 100

7.9 POWERPLANT

Cowl flap

The first paragraph is amended to read:

For operation of the cowl flap, there is a T-grip or a circular button on the center console next to the cabin heat button. If the T-grip is installed, then turn it 90° clockwise the arrest it; if the circular button is installed, push the center portion to release the retainer and move the button.