

VORGESCHRIEBENE TECHNISCHE MITTEILUNG

NR. MSB 36-060/3

ERSETZT TM NR. 60/2

MANDATORY SERVICE BULLETIN

NO. MSB 36-060/3

SUPERSEDES SB NO. 60/2

I TECHNISCHE ANGABEN

I.1 Kategorie

Vorgeschrieben.

I.2 Betroffene Flugzeuge

HK 36	alle Werknummern
HK 36 R	alle Werknummern
HK 36 TS	alle Werknummern
HK 36 TC	alle Werknummern
HK 36 TTS	alle Werknummern
HK 36 TTC	alle Werknummern
HK 36 TTC-ECO	alle Werknummern

I.3 Dringlichkeit

Nicht anwendbar.

I.4 Gegenstand

Revisionsstand des Flughandbuchs.

I.5 Anlass

Diese Technische Mitteilung wird durch die aktuellen LOADP Dok. Nr. 3.05.01 Chapter 1 ersetzt.
Diese Technische Mitteilung wird zurückgezogen.

I TECHNICAL DETAILS

I.1 Category

Mandatory.

I.2 Airplanes affected

HK 36	all serial numbers
HK 36 R	all serial numbers
HK 36 TS	all serial numbers
HK 36 TC	all serial numbers
HK 36 TTS	all serial numbers
HK 36 TTC	all serial numbers
HK 36 TTC-ECO	all serial numbers

I.3 Time of Compliance

Not applicable.

I.4 Subject

Revision status of Airplane Flight Manual.

I.5 Reason

This Service Bulletin is replaced by the current LOADP Doc. No. 3.05.01 Chapter 1.
This Service Bulletin is revoked.

I.6 Mitgeltende Unterlagen

Keine.

I.7 Genehmigung

Die technischen Informationen in diesem Dokument sind auf Grundlage des EASA Design Organisation Approval ref. EASA.21J.052 genehmigt worden.

I.8 Tätigkeiten/Anweisungen

Keine.

I.9 Masse und Schwerpunktlage

Nicht betroffen.

III HINWEISE

Im Falle von Unklarheiten, kontaktieren Sie Diamond Aircraft Industries.

I.6 Concurrent Documents

None.

I.7 Approval

The technical information contained in this document has been approved under the authority of EASA Design Organization Approval ref. EASA.21J.052.

I.8 Accomplishment/Instructions

none.

I.9 Mass (Weight) and CG

Not affected.

III REMARKS

In case of doubt, contact Diamond Aircraft Industries.