

SERVICE BULLETIN



Diamond
AIRCRAFT

Service Bulletin No.: DA20-12-01, Rev. 0

Date Issued: June 19, 1996

Title: Installation, Fuel Pipette and Fixed Provision

Page: 1 of 3

1. **ATA Code:** 1200
2. **Effectivity:** All DA20-A1 Katana up to and including S/N 10155
3. **General:** This bulletin describes the installation of the Fuel Pipette including fixed provisions
4. **Compliance:** Recommended upon receipt of the Fuel Pipette.
5. **Approval:** N/A
6. **Labor:** 0.25 man-hours
7. **Material:**
- | <u>Description:</u> | <u>Part Number:</u> | |
|---------------------|---------------------|---------|
| Pipette, Fuel | 20-1200-02-00 | (Qty 1) |
| Clip, Gripper | 086-003 | (Qty 2) |

One kit will provided for each A/C free of charge by ordering Material Kit DA20-12-01MK.

8. **Special Tools:** N/A
9. **References:** DA 20 Katana Maintenance Manual

10. Accomplishment Instructions:

- 10.1 Remove the two baggage net retaining machine screws indicated by the arrows in Figure 1 (two of six that attach the baggage net to the Backrest).
- 10.2 Re-install the screws, with the Gripper Clips (P/N 086-003) as shown in Figure 2.
- 10.3 Take the Fuel Pipette (P/N 20-1200-02-00) and clip into place as shown in Figure 2.

SERVICE BULLETIN



Diamond
AIRCRAFT

Service Bulletin No.: DA20-12-01, Rev. 0

Date Issued: June 19, 1996

Title: Installation, Fuel Pipette and Fixed Provision

Page: 2 of 3




Figure 1

SERVICE BULLETIN



Service Bulletin No.: DA20-12-01, Rev. 0

Date Issued: June 19, 1996

Title: Installation, Fuel Pipette and Fixed Provision

Page: 3 of 3




Figure 2

11. Weight and Balance: Negligible

12. Electrical Load Data: Not applicable

13. Credit: None

To obtain satisfactory results, procedures specified in this service information letter must be accomplished in accordance with accepted methods and current government regulations. Diamond Aircraft Industries Inc. cannot be responsible for the quality of work performed in accomplishing the requirements of this service information letter.

Diamond Aircraft Industries Inc. 1560 Crumlin Sideroad, London, Ontario, Canada N5V 1S2
Phone: (519) 457-4041 Fax: (519) 457-4045