

## TEMPORARY REVISION

### TR-MÄM-20-475

### New Fire Extinguisher

This Temporary Revision TR-MÄM-20-475 is approved in conjunction with the Mandatory Design Change Advisory MÄM 20-475 and is valid in conjunction with the latest revision of the DV 20 E Airplane Flight Manual until this Temporary Revision has been incorporated into the Airplane Flight Manual.

The limitations and information contained herein either supplement or, in the case of conflict, override those in the Airplane Flight Manual or its previous Temporary Revisions.

The technical information contained in this document has been approved under the authority of DOA No. EASA.21J.052.

Doc. No.	Chapter	Affected Pages
4.01.25-E	3	3-26a
	4	4-6a
	6	6-14a

#### Instruction

- Print this document on yellow paper (single-sided).
- Insert this cover page as the first page of the AFM.
- Insert the other pages of this TR in front of the corresponding AFM pages.

Doc. No. 4.01.25-E	TR-MÄM-20-475	08-Aug-2023	Cover Page
--------------------	---------------	-------------	------------

### **3. EMERGENCY PROCEDURES**

#### **3.8 SMOKE AND FIRE**

*The following note is added:*

#### **NOTE**

- The fire extinguisher is located in the baggage compartment behind the co-pilot's seat.
- To release the fire extinguisher out of the fire extinguisher mount, open the holding strap and pull the fire extinguisher out.

## **4. NORMAL OPERATING PROCEDURES**

### **4.3 CHECKLISTS FOR NORMAL OPERATING PROCEDURES**

#### **4.3.2 PRE-FLIGHT INSPECTION**

##### I. Cabin Check

*The following item is amended to read:*

- I 26) Fire extinguisher . . . . . stowed and secured
- I pressure in green arc

## 6. MASS AND BALANCE

### 6.5 EQUIPMENT LIST AND EQUIPMENT INVENTORY

*The following item is added to the Equipment list:*

Airplane Serial No.:		Registration:		Date:		Mass		Lever Arm	
Description	Type	Part No.	Manufacturer	S/N	installed	lb	kg	in	m
Fire extinguisher		337TS	Amerex					26.4	0.67